

e-Authorization

4/28/20
01:00:07 PM

3-Authorization number PA03406242 Reference no: 70267 Status: Approved Approved by steic Approved date 4/10/2023
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSGG19NWW10916 5/11/2022
600 E Baseline Rd
Evansville, IN 47725

Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
-------------------	-------------	--------	-----------	-------------------	-----------------	-----	---------------	--------------------------------

1	2203314D Sealant - Roof On	0.00	18.00	12.00		1	0.30	Complaint: THERE IS A LARGE AMOUNT OF WATER IN THE AREA OF THE MURPHY BED. THE MATTRESS IS SOAKED AND MOLDING. AND THE CARPET IS WET AND MOLDING. CUSTOMER HAS NOTICED THAT THE PASS THROUGH IS DRY. THERE IS MOLD GROWING UP THE WALL AS WELL Cause: AFTER CHECKING OUT THE ROOF. FOUND A FEW SPOTS THAT I HAD TO DICOR. TOOK PICS. FRONT TRIM AROUND SATILITE AND REAR TRIM. TOOK PICS OF THE BED. NEED TO TAKE OUT 12V AND 110 ON LOWER CABINETS. NEED TO REMOVE ALL THE CABINETS BY THE BED. REMOVE WALL PANELS. CUT AND INSTALL WALL PANELS AND BATON STRIPS. 18 HRS LABOR Correction: AFTER CHECKING OUT THE ROOF. FOUND A FEW SPOTS THAT I HAD TO DICOR. TOOK PICS. FRONT TRIM AROUND SATILITE AND REAR TRIM. TOOK PICS OF THE BED. NEED TO TAKE OUT 12V AND 110 ON LOWER CABINETS. NEED TO REMOVE ALL THE CABINETS BY THE BED. REMOVE WALL PANELS. CUT AND INSTALL WALL PANELS AND BATON STRIPS. 18 HRS LABOR
---	----------------------------	------	-------	-------	--	---	------	--

KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
KRV - Discussed repairs with Ben Hoffman

2	2201514D Awning & Gutter F	0.00	0.20	0.10		1	0.10	Complaint: WATER RUNS DOWN BETWEEN THE AWNING AND THE COACH WHEN IT IS RAINING. Cause: PUT SILICONE OVER SCREW ON AWNING. TOOK PICS Correction: PUT SILICONE OVER SCREW ON AWNING. TOOK PICS
---	----------------------------	------	------	------	--	---	------	--

3	1201114A Enclosed Underbr	0.00	0.20			1	0.50	KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual. Complaint: UNDERBELLY IS COMING LOOSE ON THE FRONT
---	---------------------------	------	------	--	--	---	------	---

r paper claims ~~only~~ use one pre-authorization number per warranty claim for
multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

4/28/20
01:00:07

KRV – Duplicate Pre-Authorization. Original Pre-Authorization was previously approved on PA03308959