

e-Authorization

4/26/20
11:03:19

Authorization number PA03410784 Reference no: 70320 Status: Approved Approved by wessi
 Address 600 E Baseline Rd Approved Retail sold on
 Name Basden's American RV VIN 4YDTSGG16NW10096 4/15/2022
 City Evansville, IN 47725

Item #	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1211406B	Slide Out Mechan	0.00	9.00	6.00		2	1.50	Complaint:THE REAR OF THE SLIDE ROOM WILL NOT GO OUT. THERE IS ALSO A SCREW THAT IS LOOSE AND PULLED AWAY ON THE OUTSIDE OF THE REAR SLIDE ROOM Cause:BRING IN AND PULL INSIDE FACUAHA AND WORK TO GETSLIDEROOM OPEN FAR ENUFF TO REMOVE SCREWS TO GET ONE END OUT OF WALL TO #s FOR PARTS ODER NEW SLIDE WORKS, CONTROL BOX IS MOUTED UNDER DRAW UNDER SLIDEROOM NOT ACSESSABLE WITH ROOM STUCK IN Correction:WILL HAVE TO REPLACE THE SLIDE SYSTEM DUE TO INSTALL THE SLIDE SYSTEM HAS FAILED..... THERE IS NOT ENOUGH ROOM TO WORK WITH VERY MUCH ON ONE SIDE OF THE ROOM PLEASE ADJUST THE TIME ACCORDINGLY
2	6100714A	Drain Lines - Was	0.00	1.00	0.20		1	0.20	Complaint:METAL SUPPORT STRAP THAT SUPPORTS SEWER DUMP HAS COME LOOSE Cause:FOUND STRP BROKEN Correction:HANGER STRAP BROKE USE PLUMMERS BANDING TO RECONET PIPE TO FRAME

KRV - NOTICE***NOTICE***NOTICE***NOTICE
 The following photos MUST be submitted with your Claim to receive payment approval.
 Eight (8) photos of the In-Wall System gear rack location after completing repairs.
 Note: Take measurements from the gear rack to the edge of the column with tape measurement pressed against the gear rack, not above or below. This measurement is best taken with the slide extended at 6 inches from the exterior of the coach and then again with the slide at full extension at all four corners for a total of 8 measurements.
 KRV - NO VCB

paper claims only use one pre-authorization number per warranty claim for
 a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

