



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70387
Promised Date:
22 APR 23

CUSTOMER WORK ORDER

WO #: 70387

Customer: 53530 - SCHWARTZ,
DUSTIN M. -

Tag:

Author: BH

Location: 0505 CHECK PREAUTH

Stock #: 11146

Stock Desc: 2023 TT KEYSTONE

COUGAR HALF-TON 26RBS

Chassis #: 4YDTCGM21PL500604

Serial #: 4YDTCGM21PL500604

Mileage:

Licence:

Invoice #:

Date In: 15 APR 23

Promised: 22 APR 23

Date Sched:

Completed: 30 APR 23

Warr. Date: 15 APR 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT - FINAL PDI ON NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Recorded all tire serial numbers. Checked roof and awning. Checked all interior lights. Checked converter output. Checked all cabinets and drawers. Added water to fresh water tank and flushed antifreeze from water lines and faucets. Performed LP drop test and set LP pressure at 11 in.wc. Operated all appliances. Checked TV Antenna, TV, Radio/CD/DVD Player and Fireplace. Made up winterizing hose and put next to water pump. All keys are missing for this unit. Made up a set of keys required for this unit. Moved unit to walk thru area for final cleaning.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
72-0818	1/2" MPT TO 1/2" PEX	1.00	N/C	N/C
KEY-G391	391 BAGGAGE DOOR KEY	1.00	N/C	N/C
20-0798	GLOBAL KEY BLANKS	2.00	N/C	N/C
219210	Seal - D Seal - EPDM - .57" x .44" - w 1/2" PSA Tape - Automotive Grade - 500'Bx	8.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LP20	20 LB. LP CYLINDER	2.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #COVER-L - Internal

COMPLAINT: INSTALL LARGE SLIDE COVER 138" TO 192"

CAUSE: COVER -L- INSTALL LARGE SLIDE COVER 138" TO 192"

CORRECTION: Mounted brackets on face of slide out. Mounted awning rail above slide out flange. Installed slide cover in awning rail. Centered over slide out. Secured in place. Removed spring locking pins. Checked operation of slide cover and slide out. Secured cover to awning rail. Cut up shipping tube and put in dumpster.



Customer #:
53530

W/O: 70387
Promised Date:
22 APR 23



Customer #:
53530



Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts Part #	Description	Qty	Price	Total
PUTTY	PUTTY TAPE - ROLL	1.00	N/C	N/C
00-0496	V000165061 13' BLK TOPPER W/HARDWARE - LIPPERT	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #COVER-L: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: FIX STRUT UNDER MASTER BED

CAUSE: FIX STRUT UNDER MASTER BED

CORRECTION: Top end of bed strut mounting block pulled off of mounting staples. Cut off all staples sticking through mattress board. Marked location of strut mounting block. Remounted block with long screws through mattress board in into strut mounting block. Reconnected strut to block. Checked operation of mattress board up and down.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	80.00

Subtotal for Job #1: 80.00

Job #2 - Warranty

COMPLAINT: FIX KITCHEN BACKSPLASH

CAUSE: FIX KITCHEN BACKSPLASH.

CORRECTION: Backsplash pulled away from wall behind kitchen sink. Reattached kitchen backsplash and corner trim.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	48.00
Z990	MISCELLANEOUS REPAIR	DKM	16.00

Subtotal for Job #2: 64.00

Job #3 - Internal

CUSTOMER WILL INSTALL AND SET UP HIS OWN HITCH

Subtotal for Job #3: 0.00

Job #WALK - Internal

COMPLAINT: WALK THRU



CORRECTION: went through unit with customer. replaced seal on door.
Estimated Amount: 180.00

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #WALK: 0.00

Job #4 - Internal

COMPLAINT: RECALIBRATE LEVELING SYSTEM

CORRECTION: front end was 3 inches too high. lowered front and recalibrated.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #4: 0.00

Parts Total: 0.00
Labour Total: 144.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 144.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 May 2023

W/O: 70387
Promised Date:
22 APR 23



Customer #:
53530

