

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	1516350
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	5ZT2CAEC9PK005476
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$160.00	<b>SITE/WAREHOUSE</b>	203 / 203
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	BCAT164BH
GREGORY A DAVIS		<b>DEALER RO #</b>	70450
15349 SHAKESPEARE DR		<b>CLAIM START DATE</b>	05/02/2023
Evansville, IN 47725		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	04/25/2023	<b>WARRANTY EXPIRATION DATE</b>	04/25/2024

## Claim Line Details

Labor Line#	Operation Code	Operational Description	
Labor Line# 1	42-622-03-01-001244	Break-A-Way Switch - Cargo Electrical/12 Volt Exterior/Service Brake System, Hydraulic & Electric/Replace	
	<b>Complaint, Cause, Correction</b>		
	Original Note : bhoffman@americanrvcenter.com, 2023-05-02 12:34:18 :: BREAK-AWAY SWITCH WIRES SMASHED ON THE FRAME. found wires were smashed and other wire was not connected, also nuts were loose on disconnect switch, rewired one wire into hot side and other wire to brakes, remounted disconnect switch.		
	<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
		0.20	\$32.00
		0.20	\$32.00
	<b>Notes</b>		
	AUTHORIZED AS REQUESTED		
Labor Line# 2	41-582-01-003617	USB Port & Charger - Marine Electrical/Audio/Replace	
	<b>Complaint, Cause, Correction</b>		
	Original Note : bhoffman@americanrvcenter.com, 2023-05-02 12:35:21 :: USB IN TOP BUNK HAS NO POWER took usb out of wall and found ground wire not connected, cut wires and reconnected, put usb back in wall.		
	<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
		0.30	\$48.00
		0.30	\$48.00
	<b>Notes</b>		
	AUTHORIZED AS REQUESTED		
Labor Line# 3	01-30-101-003418	Interior Door Jam, Casing, Trim - Replace/Interior/Interior Doors	
	<b>Complaint, Cause, Correction</b>		
	Original Note : bhoffman@americanrvcenter.com, 2023-05-02 12:36:00 :: WOOD UNDER CABINET HAS FELL DOWN stapled panel back in place.		
	<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
		0.20	\$32.00
		0.20	\$32.00
	<b>Notes</b>		
	AUTHORIZED AS REQUESTED		
Labor Line# 4	02-30-101-001076	Hinged Passage Door - Adjust/Interior/Interior Doors	
	<b>Operational Description</b>		
	Hinged Passage Door - Adjust/Interior/Interior Doors		

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2023-05-02 12:38:28 :: BATHROOM DOOR WONT LATCH took of latch and repositioned to catch door,all good.

<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$32.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.00	<b>Appr Labor Amt</b>	\$0.00

**Notes**

DUPLICATE CLAIM - THIS WAS ALREADY PAID ON CLAIM 1454842.

**Labor  
Line# 5**

**Operation Code**

43-564-11-15-003534

**Operational Description**

Thermostat Wiring - Bus Electrical/Air Conditioning/Electrical/Repair or Replace

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2023-05-02 12:39:50 :: THEROMSTATE IS LOOSE took off cover and pulled out screws and moved thermostat and reshot screws in wall.

<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$32.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$32.00

**Notes**

AUTHORIZED AS REQUESTED

**Submitted**

Labor Amt	\$176.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$176.00</b>

**Approved**

Labor Amt	\$144.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$144.00</b>

**DEALER**

**DATE**

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER**

**DATE**

**SIGNATURE**

All repairs described have been inspected and are satisfactory.