

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS CLAIM CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 4X4TCKB29NX157405 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 017 / 017A ITEM # ACKT264DBH DEALER RO # 70452 CLAIM START DATE 04/24/2023 CLAIM END DATE 01/01/1900	Authorized 1506553 017 / 017A ACKT264DBH 70452 04/24/2023 01/01/1900
Labor rate: \$160.00 OWNER INFORMATION RAY W KRACK 2522 S STATE RT 61 Boonville, IN 47601 USA		
Retail Date of Purchase 08/27/2022	WARRANTY EXPIRATION DATE 08/27/2023	

Claim Line Details

Labor

Line# 1	Operation Code 60-139-01-00-001542	Operational Description Single Handle Kitchen Faucet - Plumbing/Kitchen (Galley) Sink/Replace/ No Tread Code								
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-04-24 14:39:18 :: REPLACE KITCHEN SINK FAUCET IT IS BROKEN TOOK PICTURES OF BROKEN FAUCET. PUT IN PO FOR NEW KITCHEN FAUCET. RECIEVED NEW KITCHEN FAUCET. UNBOXED NEW FAUCET. DISASSEMBLED BROKEN FAUCET AND WATER LINES. INSTALLED NEW FAUCET. WILL TEST FAUCET DURING DEWINTERIZATION. NO LEAKS WERE FOUND AFTER REPLACING FAUCET.									
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.50</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$80.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.50</td> <td>Appr Labor Amt</td> <td>\$80.00</td> </tr> </table>	Dlr Sub Hrs	0.50	Sub Labor Amt	\$80.00	Appr Hrs	0.50	Appr Labor Amt	\$80.00
Dlr Sub Hrs	0.50	Sub Labor Amt	\$80.00							
Appr Hrs	0.50	Appr Labor Amt	\$80.00							

Notes

Please attach picture of the white tag on the faucet hose lying flat before sending to processing

Labor

Line# 2	Operation Code RC-042-15-00-004215	Operational Description 22V556, 2022-368 - LCI AWNINGS 20E-055 - INSPECTION, REPAIR OR REPLACEMENT ONLY - Recall/Awning/Repair or Replace/No Tread Code								
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-04-24 14:40:33 :: #22-434 LIPPERT AWNING RECALL (INSPECTION) GOT A SCISSOR LIFT TO CHECK THE LENGTH OF THE AWNING. RAN AWNING OUT ABOUT 6 INCHES. TOOK PICTURES OF AWNING. ON THE FRONT SIDE OF AWNING HAS A SMALL TEAR JUST ABOVE THE LED LIGHTS. NO OTHER DAMAGE WAS FOUND WHILE INSPECTING AWNING. RETRACTED THE AWNING WHEN DONE WITH INSPECTION. Additional Note : bhoffman@americanrvcenter.com, 2023-04-24 14:41:49 :: PLEASE LOOK AT AND LET ME KNOW									
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.30</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$48.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.30</td> <td>Appr Labor Amt</td> <td>\$48.00</td> </tr> </table>	Dlr Sub Hrs	0.30	Sub Labor Amt	\$48.00	Appr Hrs	0.30	Appr Labor Amt	\$48.00
Dlr Sub Hrs	0.30	Sub Labor Amt	\$48.00							
Appr Hrs	0.30	Appr Labor Amt	\$48.00							

Notes

Submitted	Labor Amt	\$128.00	Approved	Labor Amt	\$128.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$128.00		Total	\$128.00

DEALER

DATE

CUSTOMER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

SIGNATURE

All repairs described have been inspected and are satisfactory.