

Claim Response

Claim: C3390784

Non-Warranty Goodwill Adjustment

Last Modified by:stutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3390784	70470	4/24/2023	4/24/2023	4YDT29D22L7241087		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	160.00	0.00	SA21-414	7/20/2019

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

5218749

Component Model: 6020

Component Serial Number: N 18 12

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: TOOK PICTURES OF LP REGULATOR FOR RECALL. RECIECED NEW LP REGULATOR WITH HOSES. REMOVED RECALLED REGULATOR WITH HOSES. PREPED NEW LP REGULATOR FOR INSTALL. INSTALLED NEW LP REGULATOR. CHECKED FOR LEAKS. Correction: TOOK PICTURES OF LP REGULATOR FOR RECALL. RECIECED NEW LP REGULATOR WITH HOSES. REMOVED RECALLED REGULATOR WITH HOSES. PREPED NEW LP REGULATOR FOR INSTALL. INSTALLED NEW LP REGULATOR. CHECKED FOR LEAKS. (Deking/KRV)		0.50	0.50	80.00	0.00	1	0.50	Approved

Submitted parts & subLet 28.75
Submitted labor & subLet 80.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 108.75

Approved parts & subLet 28.75
Approved labor & subLet 80.00
Approved freight: 0.00
Tax: 0.00
Total approved: 108.75