

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70513
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11149 - 2023 COUGAR 320RDS 4YDFCGR23P2505962

VIN: 4YDFCGR23P2505962 HIN: SER#: 4YDFCGR23P2505962

Mileage: 0 Work Order Comp: 31 MAY 23

Auth. No: Dealer #: 1194

Warr. Date: Work Order Date: 27 APR 23 Inv #: 391832

WO #	Job #	Description	JOB INFORMATION
70513	2	ONE 751 KEY IS MISSING AND THIS WAS NOTED ON THE DELIVERY.	
70513	3	THE BOTTOM BOARD IS CRACKED ON ONE OF THE DINING CHAIRS. bottom board on chair is cracked get and open box unpack chair, put in unit, remove broken chair	
70513	5	THE WALL BY THE PANTRY HAS A DARK MARK ON IT WHERE IT HAS BEEN RUBBED. THIS WAS NOTED ON DELIVERY. back slasp over cabinet has rub mark try to clean mark off wall board is damaged need new board for back splash find unit on sales lot close up and bring in, find parts in crate and box, open and check parts, remove batten stripa , pull nails, peal off back splash, cut new back slpash, find glue, install back splah, install batting strips,	
70513	6	DINING TABLE TOP HAS A SCREW SHOT THROUGH THE TOP remove bad table top, install new top, close up unit and put unit out on sale lot and open up	
70513	4	THE CABINET DOORS BY THE RADION HAVE LATCHES THAT ARE BENT AND RUBBING WHICH IS DAMAGING THE CABINET DOORS. THIS WAS NOTED ON THE DELIVERY was installed in wrong place remove latches off of doors, straten latches, fill screw holes with wood and glue, reset latches on doors	

Claim : 70513

```

*****
WO #      Job #   Description      JOB INFORMATION
*****

```

```

*****
Part No   Job#   Description      PARTS      Qty      Price      Total
*****
L200      2     L200 2-pk 751 REPLACEMENT KEY      1.00      5.08      5.08
657739    3     Chair - Dinette - All Decors - Ge  1.00     131.10     131.10
665283    5     Countertop - Backsplash - 4' x 8'  1.00     324.40     324.40
651615    6     Table - Top Only - 26" x 40" - Fa  1.00     262.10     262.10

```

```

*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      2     MISCELLANEOUS REPAIR      0.10     160.00     16.00
Z990      3     MISCELLANEOUS REPAIR      0.10     160.00     16.00
Z990      3     MISCELLANEOUS REPAIR      0.00     160.00     0.00
Z990      3     MISCELLANEOUS REPAIR      0.00     160.00     0.00
Z990      5     MISCELLANEOUS REPAIR      1.00     160.00     160.00
Z990      5     MISCELLANEOUS REPAIR      0.00     160.00     0.00
Z990      5     MISCELLANEOUS REPAIR      0.00     160.00     0.00
Z990      5     MISCELLANEOUS REPAIR      0.00     160.00     0.00
Z990      6     MISCELLANEOUS REPAIR      0.20     160.00     32.00
Z990      4     MISCELLANEOUS REPAIR      0.20     160.00     32.00

```

```

*****
Excode    Job#   Description      EXTRAS      Qty      Price      Total
*****
FRT       3     FREIGHT FOR TABLE AND COUNTER TOP  1.00     183.25     183.25
FRT       3     FREIGHT FOR CHAIR      1.00     114.56     114.56

```

```

Parts Total:      722.68
Labour Total:     256.00
Sublet Total:      0.00
Extras Total:     297.81

```

>>>> Claim Total: 1,276.49

Customer Signature: _____

Date: _____