



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70513
Promised Date:
24 MAY 23

CUSTOMER WORK ORDER

WO #: 70513

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0601 CHECK STATUS WITH
JP

Stock #: 11149
Stock Desc: 2023 5W KEYSTONE
COUGAR 320RDS
Chassis #: 4YDFCGR23P2505962
Serial #: 4YDFCGR23P2505962
Mileage: 0
Licence:

Invoice #:
Date In: 27 APR 23
Promised: 31 MAY 23
Date Sched:
Completed: 31 MAY 23
Warr. Date:



Customer #: 1000
BASDEN'S AMERICAN RV,



Job #PDINFW - Internal

PDI - NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #2 - Warranty

ONE 751 KEY IS MISSING AND THIS WAS NOTED ON THE DELIVERY.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	16.00

Parts

Part #	Description	Qty	Price	Total
L200	L200 2-pk 751 REPLACEMENT KEY	1.00	5.08	5.08

Subtotal for Job #2: 21.08

Job #3 - Warranty

COMPLAINT: THE BOTTOM BOARD IS CRACKED ON ONE OF THE DINING CHAIRS.

CAUSE: bottom board on chair is cracked

CORRECTION: get and open box unpack chair, put in unit, remove broken chair

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	16.00
Z990	MISCELLANEOUS REPAIR	JP	0.00
Z990	MISCELLANEOUS REPAIR		0.00

Parts



Part #	Description	Qty	Price	Total
657739	Chair - Dinette - All Decors - Georgia Chair - Carb 2 - Bubka Oatmeal - Cocoa Oa	1.00	131.10	131.10

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT FOR TABLE AND COUNTER TOP	1.00	183.25	183.25
FRT	FREIGHT FOR CHAIR	1.00	114.56	114.56

Subtotal for Job #3: 444.91

Job #4 - Warranty

COMPLAINT: THE CABINET DOORS BY THE RADION HAVE LATCHES THAT ARE BENT AND RUBBING WHICH IS DAMAGING THE CABINET DOORS. THIS WAS NOTED ON THE DELIVERY

CAUSE: was installed in wrong place

CORRECTION: remove latches off of doors, straten latches, fill screw holes with wood and glue, reset latches on doors

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	32.00

Subtotal for Job #4: 32.00

Job #5 - Warranty

COMPLAINT: THE WALL BY THE PANTRY HAS A DARK MARK ON IT WHERE IT HAS BEEN RUBBED. THIS WAS NOTED ON DELIVERY.

CAUSE: back slasp over cabinet has rub mark

CORRECTION: try to clean mark off wall board is damaged need new board for back splash find unit on sales lot close up and bring in, find parts in crate and box, open and check parts, remove batten stripa , pull nails, peal off back splash, cut new back splash, find glue, install back splash, install batting strips,

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	160.00
Z990	MISCELLANEOUS REPAIR	JP	0.00
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	JP	0.00

Parts

Part #	Description	Qty	Price	Total
665283	Countertop - Backsplash - 4' x 8' - Styrene - Patterned Herringbone - w/Grey Grout (Print Only)	1.00	324.40	324.40

Subtotal for Job #5: 484.40

Job #6 - Warranty

COMPLAINT: DINING TABLE TOP HAS A SCREW SHOT THROUGH THE TOP

CORRECTION: remove bad table top, install new top, close up unit and put unit out on sale lot and open up

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	32.00

Parts

Part #	Description	Qty	Price	Total
651615	Table - Top Only - 26" x 40" - Fat Boy - Carb 2 - Bandsaw Design - Cocoa Oak	1.00	262.10	262.10

W/O: 70513
Promised Date: 31 MAY 23



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #6: 294.10

W/O: 70513
Promised Date: 31 MAY 23

Parts Total:	722.68
Labour Total:	256.00
Sublet Total:	0.00
Extras Total:	297.81
WORK ORDER TOTAL:	1,276.49

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 31 May 2023



Customer Work Order

Customer #: 1000
BASDENS AMERICAN RV,

