



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70548
Promised Date:
24 MAY 23

CUSTOMER WORK ORDER

WO #: 70548

Customer: 52977 - LAWYER, TRAVIS R.
- 812-827-1920

Tag:

Author: BJW

Location: 0627 BH TO CLOSE WHEN HE
GETS BACK

Stock #: 11084

Stock Desc: 2022 5W FOREST RIVER
SABRE 37FLH

Chassis #: 5ZT3SR2B3N6110618

Serial #: 5ZT3SR2B3N6110618

Mileage: 0

Licence:

Invoice #:

Date In: 02 MAY 23

Promised: 31 MAY 23

Date Sched:

Completed: 26 JUN 23

Warr. Date: 27 AUG 22

Job #1 - Warranty

COMPLAINT: CHECK FRIDGE NOT COOLING AND FREEZING UP

CAUSE: Fridge freezing up

CORRECTION: Open slide rooms so So fridge could fit While removing bad fridge and installing new fridge. Removed table and chairs and the mounts that hold the fridge in. Pulled fridge out of cabinets and disconnected the power to the back of the fridge. Laid cardboard on floor to set fridge on. Had to remove the window in the slide room to slide the fridge out with the Forktruck. Put new fridge on Forktruck and brought up into the window. Put window back in slide room. Move new fridge to cabinet area and tied up wires and put into place of cabinet. Put dining table and chairs back in place and screw the dining table back to the floor. Cleaned up the mess of cardboard that we used to run the fridge across to protect the floors. Applied new silicone at the top of the window to capsule since I had to cut the old silicone to remove the window. Put thermometers inside fridge and will let sit to check temperature later. How to remove the buttons from the old fridge and restick to the new fridge with new? Double sided tape so the doors will stay shut during travel. Take pictures of progress. We'll check the fridge temp the next day. Couldn't get old fridge to duplicate as customers stated this customer needs fridge back ASAP. Customer does live in camper full time. After new fridge was installed set fridge to smart settings, Which gave me a setting in the fridge of forty degrees and the freezer negative zero which bottles of antifreeze were accurate with Thermometers.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	320.00

Parts

Part #	Description	Qty	Price	Total
F100300311	REFRIGERATOR, EVERCHILL 16.2 CUFT, 1	1.00	1,802.63	1,802.63

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-REFER	1.00	113.88	113.88

Subtotal for Job #1: 2,236.51

Customer #: 52977
LAWYER, TRAVIS R.



W/O: 70548
Promised Date: 31 MAY 23

Parts Total:	1,802.63
Labour Total:	320.00
Sublet Total:	0.00
Extras Total:	113.88
WORK ORDER TOTAL:	2,236.51

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Jun 2023



Customer #: 52977
LAWYER, TRAVIS R.

