



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70575
Promised Date:
12 MAY 23

CUSTOMER WORK ORDER

WO #: 70575

Customer: 53613 - BRUCE, LOUIS D. -
812-459-9796

Tag:

Author: BH

Location: 0520 CHECK PREAUTH

Stock #: 11020

Stock Desc: 2023 TT COACHMEN
CATALINA SUMMIT SERIES 164BH

Chassis #: 5ZT2CAEC3PK005473

Serial #: 5ZT2CAEC3PK005473

Mileage:

Licence:

Invoice #:

Date In: 06 MAY 23

Promised: 12 MAY 23

Date Sched:

Completed: 17 MAY 23

Warr. Date: 12 MAY 23

Job #FPDINTT - Internal

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
CUR25013	1/4IN DIAMETER SAFETY PIN W/ 12IN CHAIN PKG	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #BCWV - Internal

BRAKE CONTROL & WIRING - VAN, SUV & CAR

Labor

Code	Description	Mechanic	Total
BCWV	BRAKE CONTROL & WIRING - VAN, SUV &	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
81783	81783 92-19 FORD/MERCURY/LINCOLN	1.00	N/C	N/C
17-0081	#51120 BRAKE CONTROL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BCWV: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Customer #: 53613
BRUCE, LOUIS D.





Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: LIGHTS BLOW FUSE WHEN WHEN 7 WAY IS HOOKED UP AND TESTED

CAUSE: LIGHTS BLOW FUSE WHEN 7 WAY IS HOOKED UP

CORRECTION: When tail lights care turned "ON" with test box the fuse blows. Removed junction box cover under front frame. Checked all wire connections. All connections good and correct. Removed both rear tail lights. Checked connections. All good and correct. Removed all rear clearance lights. Checked connections All good and correct. Still blowing fuse in test box. Cut all lights loose from wiring. Started checking wires from light to light. Found that positive wire from roadside left clearance to next one over was shorted. Fished a new positive wire between these two lights. Taped off old wire at both ends. Connected lights together. Lights now work. Remounted all rear lights and resealed. Checked lights again after reassembly. All working ok.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	240.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	160.00

Subtotal for Job #1: 480.00

Parts Total: 0.00
 Labour Total: 480.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 480.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 17 May 2023

