



Warranty Authorization Form

Date: 5/17/2023

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 38751 Unit: 7M5FV3623PA007563
Series: Valor Model: 2023VAL30A20
Notes:
Status: Approved

Dealer Information

American RV (812) 867-5200	Basden RV Center, Inc. DBA/ American RV 600 E Baseline Rd, Evansville, IN 47725	Requestor: Ben Hoffman Return Fax #: Email: bhoffman@americanrvcenter.com
-------------------------------	---	---

Operation Line 1

Flat Rate Code: 20038 SPRAY PORT - REPLACE (part return in *Fault Code:* VENDOR US)

Serial #: *Model #:* *Notes:*

Problem: EXTERIOR SPRAY PORT LID WON'T CLOSE

Time Requested: .2

Cause: EXTERIOR SPRAY PORT LID WON'T CLOSE.

Time Allowed: .2

Remedy: Spray port is warped and lid won't close. Removed original spray port. Cleaned old silicone from around mounting hole. Installed new spray port. Resealed with clear silicone. Lid closes on new spray port.

Sublet Repairs: 0.00

Part Return Req: Yes

Status: Approved