

Claim Response

Claim: C3404943

Non-Warranty Goodwill Adjustment

Last Modified bystutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3404943	70614	5/11/2023	5/11/2023	4YDT27525L3100217		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	160.00	0.00	SA21-414	6/24/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

5218749

Component Model: 6020

Component Serial Number: N 18 17

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory	21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: took pictures of recall lp regulator. removed lp regulator then put new lp regulator in place tightened fittings. took pictures of new lp regulator. Correction: took pictures of recall lp regulator. removed lp regulator then put new lp regulator in place tightened fittings. took pictures of new lp regulator. (Deking/KRV)		0.50	0.50	80.00	0.00	1	0.50	Approved

Submitted parts & subLet 28.75
Submitted labor & subLet 80.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 108.75

Approved parts & subLet 28.75
Approved labor & subLet 80.00
Approved freight: 0.00
Tax: 0.00
Total approved: 108.75