

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 70641  
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725  
Phone:  
Stock Number: 10761 - 2023 SPRINGDALE 220RD 4YDTSGK23P3103207  
VIN: 4YDTSGK23P3103207 HIN: SER#: 4YDTSGK23P3103207  
Mileage: 0 Work Order Comp: 30 JUN 23  
Auth. No: Dealer #: 1194  
Warr. Date: Work Order Date: 15 MAY 23 Inv #: 393424

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
70641 4 CITY WATER INLET IS LEAKING  
CITY WATER INLET IS LEAKING.  
City water inlet is leaking on back side of check valve. Removed  
fitting to check for cone washer. Found fitting had been screwed  
onto check valve with a piece of metal shaving next to cone  
washer. Removed cone washer and metal shaving. Installed new  
cone washer and reassembled hose to fitting. Connected to city  
water and checked fitting for leak. No leak found.  
  
70641 1 BATHROOM DOOR HITTING FRAME  
BATHROOM DOOR HITTING FRAME.  
Plastic door frame is bowed and door is hitting when closing.  
Added screw to secure plastic door frame to door opening in wall.  
  
70641 2 ENTRY DOOR HITTING FRAME  
ENTRY DOOR HITTING FRAME.  
Could not find a place where door was hitting frame. Lubed  
hinges and adjusted latch plate. Door closes ok.  
  
70641 3 BATTERY DEAD ON LOT AND HAS SOLAR. CHECK AND FIND OUT IF PANEL  
IS CHARGING  
BATTERY BDEAD ON LOT AND HAS SOLAR. CHECK AND FIND PROBLEM.  
Removed connector from solar panel to roof mounted terminal.  
Checked voltage from solar panel. Meter showed 45.8  
volts. Problem is from roof mounted terminal to controller in  
front compartment. I REMOVED THE COVER ON THE ROOF TO CHECK THE

Claim : 70641

\*\*\*\*\*

WO # Job # Description JOB INFORMATION

\*\*\*\*\*

WIRING COLORS. I FOUND THAT THE SOLAR WIREING CHANGES TO GREEN AND BLACK. GREEN IS POS. AND BLACK IS NEG. I FOUND THAT THE CHARGE CONTROLER HAD THE PANEL WIRED WITH THE BLACK AS POS. AND GREEN AS NEG. I REWIRED THE CHARGE CONTROLER AND NOW THE SYSTEM IS WORKING AS IT SHOULD. I CHECKED THE CHARGE CONTROLER WITH THE APP AND VOLTMETER.

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
ESC06435	4	CONE WASHER SWIVEL SEAL		1.00	0.18	0.18

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISCELLANEOUS REPAIR		0.30	160.00	48.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	3	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	3	MISCELLANEOUS REPAIR		0.10	160.00	16.00
Z990	3	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	3	MISCELLANEOUS REPAIR		0.10	160.00	16.00
Z990	3	MISCELLANEOUS REPAIR		0.00	160.00	0.00

Parts Total: 0.18  
Labour Total: 144.00  
Sublet Total: 0.00  
Extras Total: 0.00

>>>> Claim Total: 144.18

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_