

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70665
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11095 - 2022 CATALINA 293QBCKLE 5ZT2CAUBXNX025891

VIN: 5ZT2CAUBXNX025891 HIN: SER#: 5ZT2CAUBXNX025891

Mileage: 0 Work Order Comp: 23 MAY 23

Auth. No: Dealer #:

Warr. Date: 23 MAY 23 Work Order Date: 17 MAY 23 Inv #: 391472

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

70665	2	LP HOSE FOR OUTSIDE STOVE IS TOO SHORT DKM INSTALL NEW HOSE	
-------	---	--	--

70665	3	DINETTE TABLE POSTS WOBBLE DINETTE TABLE POSTS WOBBLE Checked floor mounting sockets. One socket broken not allowing post to lock in. Removed black broken socket and replaced with an aluminum colored socket. Changed other floor socket to match replacement socket. Also factory posts will not lock into old or new sockets. Replaced both posts with silver posts to match floor sockets.	
-------	---	---	--

70665	4	TV WILL NOT PICK UP CHANNELS TV WILL NOT PICK UP CHANNELS. Checked all cables on back of TV booster. All are in correct locations. (THATS A FIRST). Removed TV antenna from its base on roof. Coax cable would not pull up and out of base to check coax end. Had to cut base loose from roof. Checked antenna coax from booster to antenna. Checks good. Checked TV with a test antenna. Picked up channels. Removed old antenna base. Cleaned off old sealer. Installed new antenna base. Installed new antenna on base. Checked operation of new antenna and TV. Now picks up channels. Sealed around base of antenna with Dicor. Remounted Booster behind TV. Checked all other TV outlets.	
-------	---	---	--

70665	1	A/C FAN MAKING LOT OF NOISE	
-------	---	-----------------------------	--

Claim : 70665

 WO # Job # Description JOB INFORMATION

 AC FAN MAKING A LOT OF NOISE.
 Removed AC shroud on roof. Base pan is bent bad. AC had to be
 dropped at factory. AC needs replaced. Removed inside plenum.
 Disconnected all wiring. Removed mounting bolts. Lifted damaged
 AC off of roof. Installed new AC on roof and aligned with hole
 in roof. Secured AC in place with mounting ring and bolts.
 Reconnected all wiring. Checked operation of AC. Putting out
 cold air. Remounted ceiling plenum and filters. New AC is
 Coleman Mod# 48204-066. Serial number 220437689.

 Part No Job# Description PARTS Qty Price Total

 172116 2 MER14TCQDMP-72P 72" HP HOSE 1/4" 1.00 59.96 59.96
 500337 3 STANDARD TABLE BASE 2.00 4.82 9.64
 500645 3 013-939 27-1/2" TABLE LEG 2.00 14.43 28.86
 410186 4 PW HAPS FREE SELF-LEVELING DICOR 1.00 6.36 6.36
 310058 1 15.0K MACH 15+-WHITE 1.00 970.52 970.52

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.05 160.00 8.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.50 160.00 80.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.00 160.00 160.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.00 160.00 160.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.53 160.00 84.80
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.47 160.00 75.20

 Excode Job# Description EXTRAS Qty Price Total

 EDF 1 ENVIROMENTAL DISPOSAL FEES 1.00 100.00 100.00

Parts Total: 1,075.34
 Labour Total: 568.00
 Sublet Total: 0.00
 Extras Total: 100.00

>>>> Claim Total: 1,743.34

Customer Signature: _____

Date: _____