



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70665
Promised Date:
22 MAY 23

CUSTOMER WORK ORDER

WO #: 70665

Customer: 1000 - BASDEN'S AMERICAN

RV -

Tag:

Author: BH

Location: DELIVERY 5-23

Stock #: 11095

Stock Desc: 2022 TT COACHMEN

CATALINA 293QBCKLE

Chassis #: 5ZT2CAUBXNX025891

Serial #: 5ZT2CAUBXNX025891

Mileage:

Licence:

Invoice #:

Date In: 17 MAY 23

Promised: 23 MAY 23

Date Sched:

Completed: 23 MAY 23

Warr. Date: 23 MAY 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT - FIN AL PDI ON NEW TRAVEL TRAILER.

CORRECTION: Moved unit into from sales lot. Installed new battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Recorded all tire serial numbers. Checked awning and roof. Operated all manual stab jacks. Checked all interior lights. Checked converter output. Added water to fresh water tank and flushed antifreeze from water pump. Connected to city water and flushed water lines and faucets. Opened by-pass on water heater and filled. Purged all air from water system. Grey water tank valve leaking. Tightened all four screws on grey water dump valve. Performed LP drop test and set LP pressure at 11 in.wc. Checked all appliances. Chceked Radio, Fireplace and TV. TV will not pick up channels. Replaced broken sewer cap. Drained all holding tanks. Water heater is full and ready to camp. Moved unit to wash bay area.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
11-0429	39463 SEWER CAP W/HOSE CONNECTION	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #MAXX - Internal

COMPLAINT: ROOF VENT COVER - INSTALLED EACH

CAUSE: MAXX - ROOF VENT COVER - INSTALLED EACH.

CORRECTION: Installed roof vent cover over bath room power vent and kitchen power vent.

Labor

Code	Description	Mechanic	Total
Z990	INSTALL MAXX AIR VENT	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,





Parts

Part #	Description	Qty	Price	Total
40431	CAMCO VENT COVER - WHITE	1.00	N/C	N/C
40431	CAMCO VENT COVER - WHITE	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #SWAP - Internal

SWAP CUSTOMER'S HITCHWORK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Warranty

COMPLAINT: A/C FAN MAKING LOT OF NOISE

CAUSE: AC FAN MAKING A LOT OF NOISE.

CORRECTION: Removed AC shroud on roof. Base pan is bent bad. AC had to be dropped at factory. AC needs replaced. Removed inside plenum. Disconnected all wiring. Removed mounting bolts. Lifted damaged AC off of roof. Installed new AC on roof and aligned with hole in roof. Secured AC in place with mounting ring and bolts. Reconnected all wiring. Checked operation of AC. Putting out cold air. Remounted ceiling plenum and filters. New AC is Coleman Mod# 48204-066. Serial number 220437689.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	84.80
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	75.20

Parts

Part #	Description	Qty	Price	Total
63140	15.0K MACH 15+-WHITE	1.00	970.52	970.52

Other Services

Code	Description	Qty	Price	Total
EDF	ENVIROMENTAL DISPOSAL FEES	1.00	100.00	100.00

Subtotal for Job #1: 1,230.52

Job #2 - Warranty

COMPLAINT: LP HOSE FOR OUTSIDE STOVE IS TOO SHORT

CORRECTION: DKM INSTALL NEW HOSE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	8.00

Parts

Part #	Description	Qty	Price	Total
06-4731	MER14TCQDMP-72P 72" HP HOSE 1/4" ID,	1.00	59.96	59.96

Subtotal for Job #2: 67.96

Job #3 - Warranty

COMPLAINT: DINETTE TABLE POSTS WOBBLE

CAUSE: DINETTE TABLE POSTS WOBBLE





CORRECTION: Checked floor mounting sockets. One socket broken not allowing post to lock in. Removed black broken socket and replaced with an aluminum colored socket. Changed other floor socket to match replacement socket. Also factory posts will not lock into old or new sockets. Replaced both posts with silver posts to match floor sockets.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	80.00

Parts				
Part #	Description	Qty	Price	Total
20-0556	STANDARD TABLE BASE	2.00	4.82	9.64
31-1564	013-939 27-1/2" TABLE LEG	2.00	14.43	28.86

Subtotal for Job #3: 118.50

Job #4 - Warranty

COMPLAINT: TV WILL NOT PICK UP CHANNELS

CAUSE: TV WILL NOT PICK UP CHANNELS.

CORRECTION: Checked all cables on back of TV booster. All are in correct locations. (THATS A FIRST). Removed TV antenna from its base on roof. Coax cable would not pull up and out of base to check coax end. Had to cut base loose from roof. Checked antenna coax from booster to antenna. Checks good. Checked TV with a test antenna. Picked up channels. Removed old antenna base. Cleaned off old sealer. Installed new antenna base. Installed new antenna on base. Checked operation of new antenna and TV. Now picks up channels. Sealed around base of antenna with Dicor. Remounted Booster behind TV. Checked all other TV outlets.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	160.00

Parts				
Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	6.36	6.36

Subtotal for Job #4: 326.36

Parts Total: 1,075.34
 Labour Total: 568.00
 Sublet Total: 0.00
 Extras Total: 100.00
WORK ORDER TOTAL: 1,743.34

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 May 2023

