



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70673
Promised Date:
24 MAY '23

CUSTOMER WORK ORDER

WO #: 70673

Customer: 52345 - TURPIN, II, DENNIS

R. - 812-779-7607

Tag: UNIT NOT HERE

Author: BH

Location: 0525 CHECK PREAUTH

Stock #: 11070

Stock Desc: 2022 5W FOREST RIVER

SABRE 36BHQ

Chassis #: 5ZT3SR1B6N6109674

Serial #: 5ZT3SR1B6N6109674

Mileage:

Licence:

Invoice #:

Date In: 17 MAY 23

Promised: 31 MAY 23

Date Sched:

Completed: 23 MAY 23

Warr. Date: 26 MAR 22

Job #2 - Warranty

COMPLAINT: SLIDEROOM IS STUCK

CAUSE: silde room will not move in or out.

CORRECTION: went underneath and opened under belly. motor and wiring look good. removed top and bottom set screws and removed motor from slide assembly. took motor to work bench and removed cover plate. clutch and gears all look good. noticed that after we removed the motor the slide room assembly moved. removed slide ram. slide ram looks good. reinstalled motor on ram and hooked up to a battery. lubricated ram and ran on and out several times on the ground. went to re installed motor and ram. when trying to install the motor back the way it was before, i realizewd that the motor is hitting on the surrounding frame. override doesnt line up with hole in frame. MOTOR ISNT ORIENTATED CORRECTLY. FOUND OUT THAT THE MOTOR HAS BEEN MOVED PREVIOUSLY. REMOVED SET SCREWS. REPOSITIONED MOTOR SO IT IS FACING"UP AND DOWN" OVERRIDE LINES UP. SECURED MOTOR TO RAM ASSMEBLY. SECURED RAM ASSEMBLY TO SLIDE ROOM ASSEMBLY. SECURED POWER WIRES TO MOTOR. SECURED RAM TO SLIDE ROOM ON THE OUTSIDE THROUGH THE FRAME. RAN SLIDE IN AND OUT SEVERAL TIMES. ADJUSTED BELL AND LOCK NUTS TO MAKE SURE ROOM PULLS IN ALL THE WAY AND PUSHES OUT ALL THE WAY. WENT DOWN TO STORAGE SHED AND GOT A PIECE OF WOOD TO RUN ALONE THE FRAME AND SECURE UNDERBELLY TO. CUT WOOD. PLACED WOOD ABOVE FRAME.SECURED UNDERBELLY TO WOOD. APPLIED EXTREME TAPE TO UNDERBELLY. CLEANED UP MESS. PARKED UNIT.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	368.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #2: 368.00

Parts Total: 0.00
Labour Total: 368.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 368.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 52345
TURPIN, II, DENNIS R.