

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	1547168
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	5ZT2CAUB0NX026077
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$160.00	<b>SITE/WAREHOUSE</b>	205 / 205
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	ACAT293QBCKLE
WAYNE S GLASER		<b>DEALER RO #</b>	70688
8933 SIX SCHOOL RD		<b>CLAIM START DATE</b>	05/26/2023
Evansville, IN 47720		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	05/23/2023	<b>WARRANTY EXPIRATION DATE</b>	05/23/2024

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b> 01-30-102-003370	<b>Operational Description</b> Ceiling Board - Cedar - Replace/Interior/Panels, Ceilings, & Interior Moldings
	<b>Complaint, Cause, Correction</b> Original Note : bhoffman@americanrvcenter.com, 2023-05-26 11:47:05 :: FIX TRIM ON SLIDE CEILING FIX TRIM ON SLIDE CEILING. Ceiling loose in 2 places. Reattached ceiling next to facia board over couch. Reattached ceiling at seam in ceiling over dinette seat. Filled all staple holes with matching putty.	
	<b>Model #</b>	<b>Dlr Sub Hrs</b> 0.20 <b>Sub Labor Amt</b> \$32.00
	<b>Serial #</b>	<b>Appr Hrs</b> 0.20 <b>Appr Labor Amt</b> \$32.00
	<b>Notes</b>	

### Labor

<b>Line# 2</b>	<b>Operation Code</b> 10-25-02-00-000398	<b>Operational Description</b> Door - Frame & Chassis/Driver or Passenger Door/Adjust/No Tread Code
	<b>Complaint, Cause, Correction</b> Original Note : bhoffman@americanrvcenter.com, 2023-05-26 11:49:23 :: FIX BATHROOM DOOR FRAME TRIM FIX BATHROOM DOOR FRAME TRIM. Plastic door jamb bowed on latch side. Pulled plastic door jamb away from frame. Applied silicone glue to bowed arew. Taped jamb tight to let silicone cure.	
	<b>Model #</b>	<b>Dlr Sub Hrs</b> 0.30 <b>Sub Labor Amt</b> \$48.00
	<b>Serial #</b>	<b>Appr Hrs</b> 0.30 <b>Appr Labor Amt</b> \$48.00
	<b>Notes</b>	

### Labor

<b>Line# 3</b>	<b>Operation Code</b> 30-101-24-00-001079	<b>Operational Description</b> Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code
	<b>Complaint, Cause, Correction</b> Original Note : bhoffman@americanrvcenter.com, 2023-05-26 11:50:56 :: FIX POCKET SLIDE DOOR RAIL FIX POCKET SLIDE DOOR RAIL. Screw missing from bottom guide. Added screw to bottom guide. Adjusted ht. of door to clear bottom guide and allow door to slide without hitting guide.	
	<b>Model #</b>	<b>Dlr Sub Hrs</b> 0.30 <b>Sub Labor Amt</b> \$48.00
	<b>Serial #</b>	<b>Appr Hrs</b> 0.30 <b>Appr Labor Amt</b> \$48.00
	<b>Notes</b>	

Labor  
Line# 4

Operation Code  
02-30-101-001076

Operational Description  
Hinged Passage Door - Adjust/Interior/Interior Doors

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2023-05-26 11:53:31 :: TIGHTEN BEDROOM DOOR KNOB AND ADJUST LATCH TIGHTEN BEDROOM DOOR KNOB AND ADJUST LATCH. Door knob loose and latch striker plate mounted too high on bedroom door at factory. Tightened door knob. Removed latch plate and remounted lower to align with door knob plunger. Checked operation of door. Now latches closed.

Model #	Dir Sub Hrs	0.30	Sub Labor Amt	\$48.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$48.00

Notes

---

**Submitted**

Labor Amt	\$176.00
Parts & Freight	\$0.00
Total	\$176.00

**Approved**

Labor Amt	\$176.00
Parts & Freight	\$0.00
Total	\$176.00

---

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

---

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.