



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70688
Promised Date:
19 MAY 23



CUSTOMER WORK ORDER

WO #: 70688

Customer: 53626 - GLASER, WAYNE S. - Stock #: 11094

(812) 430-4715

Tag:

Author: BH

Location: 0602 CHECK PREAUTH

Stock Desc: 2022 TT COACHMEN

CATALINA 293QBCKLE

Chassis #: 5ZT2CAUB0NX026077

Serial #: 5ZT2CAUB0NX026077

Mileage:

Licence:

Invoice #:

Date In: 19 MAY 23

Promised: 23 MAY 23

Date Sched:

Completed: 30 MAY 23

Warr. Date: 22 MAY 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT - FINAL PDI ON NEW TRAVEL TRAILER.

CORRECTION: Moved into shop from sales lot. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Recorded all tire serial numbers. Checked roof and awning. Checked power cord. Checked converter output. Operated all stab jacks. Checked entry door steps. Checked all interior lights. Dewinterized unit. Added water to fresh water tank and flushed water pump. Connected to city water and flushed water lines and faucets. Opened by-pass on water heater. Filled water heater and purged air from from water system. Performed LP drop test and set LP pressure at 11 in.wc. Checked TV operation at all locations. Antenna cable connected to wrong outlet on TV booster. Connected to correct outlet. TV now picks up channels. Drained all holding tanks. Retracted all stab jacks. Replaced missing awning light controller. Moved unit to wash bay.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	2.00	N/C	N/C
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #BATTERY - Internal

COMPLAINT: INSTALL 2ND BATTERY

CAUSE: BATTERY - INSTALL 2ND BATTERY.

CORRECTION: Remounted original battery box on frame to make room for second battery box. Mounted second battery box. Modified both boxes. Installed 2 new batteries. Made up cables to connect together.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Customer #: 53626
GLASER, WAYNE S.



Subtotal for Job #BATTERY: 0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: SWAP - SWAP CUSTOMERS HITCHWORK.

CORRECTION: Removed brackets from trade. Mounted brackets on new unit at same dims.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Warranty

COMPLAINT: FIX TRIM ON SLIDE CEILING

CAUSE: FIX TRIM ON SLIDE CEILING.

CORRECTION: Ceiling loose in 2 places. Reattached ceiling next to facia board over couch. Reattached ceiling at seam in ceiling over dinette seat. Filled all staple holes with matching putty.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: FIX BATHROOM DOOR FRAME TRIM

CAUSE: FIX BATHROOM DOOR FRAME TRIM.

CORRECTION: Plastic door jamb bowed on latch side. Pulled plastic door jamb away from frame. Applied silicone glue to bowed arew. Taped jamb tight to let silicone cure.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00

Subtotal for Job #2: 48.00

Job #3 - Warranty

COMPLAINT: FIX POCKET SLIDE DOOR RAIL

CAUSE: FIX POCKET SLIDE DOOR RAIL.

CORRECTION: Screw missing from bottom guide. Added screw to bottom guide. Adjusted ht. of door to clear bottom guide and allow door to slide without hitting guide.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00

Subtotal for Job #3: 48.00

Job #4 - Warranty

COMPLAINT: TIGHTEN BEDROOM DOOR KNOB AND ADJUST LATCH

CAUSE: TIGHTEN BEDROOM DOOR KNOB AND ADJUST LATCH.

CORRECTION: Door knob loose and latch striker plate mounted too high on bedroom door at factory.

W/O: 70688
Promised Date: 23 MAY 23



Customer #: 53626
GLASER, WAYNE S.



Tightened door knob. Removed latch plate and remounted lower to align with door knob plunger. Checked operation of door. Now latches closed.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00
Subtotal for Job #4:			48.00

Job #5 - Internal

COMPLAINT: PUT TURN HANDLE ON KITCHEN BLIND

CAUSE: PUT TURN HANDLE ON KITCHEN BLIND.

CORRECTION: Kitchen window blind adjustment rod not installed a factory. Mounted rod on blind adjustment hook.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #5:			0.00

Job #6 - Internal

COMPLAINT: CLEAN SPOTS ON BUNKHOUSE CUSHIONS

CAUSE: CLEAN SPOTS ON BUNKHOUSE CUSHIONS.

CORRECTION: Wash Bay to clean spots from cushions.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #6:			0.00

Job #7 - Internal

SEE JAMES OR BEN FOR ANY INFO ABOUT NUMBERED JOBS

Subtotal for Job #7: 0.00

Job #8 - Internal

COMPLAINT: BRET TO ADD SCREWS TO SUPPORT THE BOTTOM OF THE SLIDE ROOM

CORRECTION: put bolts in lower frame of slideroom

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Subtotal for Job #8:			0.00

Job #9 - Internal

COMPLAINT: INSTALL NEW QUICK CONNECT HOSE. ORIGINAL IS TOO SHORT

CAUSE: INSTALL NEW QUICK CONNECT HOSE. ORIGINAL TOO SHORT.

CORRECTION: Original LP hose to outside grille too short to reach quick connect on frame. Installed new longer quick connect hose.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

W/O: 70688
Promised Date: 23 MAY 23



Customer #: 53626
GLASER, WAYNE S.



Part # Description Qty Price Total
06-4731 MER14TCQDMP-72P 72" HP HOSE 1.00 N/C N/C
1/4" ID, QD X 1/4" QD MALE

Subtotal for Job #9: 0.00

Parts Total: 0.00
Labour Total: 176.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 176.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 May 2023

W/O: 70688
Promised Date: 23 MAY 23



Customer #: 53626
GLASER, WAYNE S.

