



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70709
Promised Date: 25 MAY 23



Customer #: 47402
BROWN, CHARLES A.



CUSTOMER WORK ORDER

WO #: 70709

Customer: 47402 - BROWN, CHARLES

A. - 812-457-9375

Tag:

Author: BH

Location: 0625 CHECK WORK

Stock #: 11194

Stock Desc: 2022 5W ALLIANCE RV

PARADIGM 310RL

Chassis #: 7M5FP362XNA006871

Serial #: 7M5FP362XNA006871

Mileage: 0

Licence:

Invoice #:

Date In: 22 MAY 23

Promised: 25 MAY 23

Date Sched:

Completed: 15 JUN 23

Warr. Date: 25 MAY 23

Job #COVER-S - Internal

COMPLAINT: Transferred to BAS*70762 on 30 MAY 23

Estimate amount was 0.00

INSTALL SMALL SLIDE COVER 66" TO 96"

CAUSE: COVER-S-INSTALL SMALL SLIDE COVER 66" TO 96".

CORRECTION: Mounted brackets on flange of slideout. Installed awning rail above slideout flange. Installed topper in awning rail and centered over slideout. Secured to brackets. Checked operation of topper and slideout. Secured topper to awning rail.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #COVER-S: 0.00

Job #COVER-L - Internal

COMPLAINT: Transferred to BAS*70762 on 30 MAY 23

Estimate amount was 0.00

INSTALL (2) LARGE SLIDE COVERS 138" TO 192"

CAUSE: COVER - L - INSTALL (2) LARGE SLIDE COVERS 138" TO 192".

CORRECTION: Install (2) Large slide toppers. Changed all factory screws that secure brackets to slide out flange. Tapped bar mounting holes in topper roller tube ends. Mounted awning rail above slideout. Installed topper in awning rail. Secured awning bars to brackets. Removed locking pins in roller tube. Checked operation of topper and slideout. Secured topper to awning rail.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #COVER-L: 0.00

Job #FPDINFW - Internal

COMPLAINT: Transferred to BAS*70762 on 30 MAY 23



Estimate amount was 0.00
FINAL PDI ON NEW FIFTH WHEELS

CAUSE: FPDINFW - FI9NAL PDI ON NEW FIFTH WHEEL.

CORRECTION: Moved unit into shop from sales lot. Installed 2 batteries and made cables to connect together. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 110 psi. Recorded all tire serial numbers. Checked both awnings. Checked roof. Checked power cord. Checked all interior lights. Checked converter output. Added water to fresh water tank and flushed water pump. Connected to city water and flushed all water lines ans faucets. Opened by-pass on water heater and filled. Purged all air from water system. Installed a temporary quick to do a LP drop test. Performed LP drop test and set LP pressure at 11 in.wc. Checked all appliances. Checked TV Antenna, both TV's, Radio and Fireplace. Drained all holding tanks. Water heater is full and ready to camp. Moved unit to washbay area.

Labor

Code	Description	Mechanic	Total
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DKM	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DKM	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DKM	N/C

Subtotal for Job #FPDINFW: 0.00

Job #1 - Internal

Transferred to BAS*70762 on 30 MAY 23
Estimate amount was 0.00
COVER TO FIT

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR A/C DOES NOT COOL COMPRESSURE DOES NOT KICK ON

CAUSE: .

CORRECTION: bring in unit, open up get new AC, remove plenum, remove wiresand control box, remove mounting bolts, remove AC off roof, found AC pan is bent and compesser bolts are damaging rubber, clean area and use rubber roof tape to cover damage to roof, put new AC in place install bolts, control box and wire up, test AC, install plemun, test AC, closes up unit and pull out

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00

Parts

Part #	Description	Qty	Price	Total
18986	Appliance - A/C - Mach 3 13.5 NDQ -	1.00	626.99	626.99

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - AC	1.00	159.82	159.82

Subtotal for Job #2: 1,026.81

Job #WALK - Internal

COMPLAINT: Transferred to BAS*70762 on 30 MAY 23
Estimate amount was 180.00
WALK THRU

CORRECTION: PULLED CAMPER FROM WASH BAY AND SET UP BY MY BAY AND PLUGGED IN AND SET UP.DID WALK THRU,ADDED LP DISCONNECT SET UP ON OUTSIDE,CUSTOMER SAID BRIAN WAS SUPPOSE TO PUT ON,ALSO SAID BRIAN WAS TO TREAT ROOF,CUSTOMER WILL BRING BACK WHEN AC COMES IN AND HAVE ROOF DONE.HOOKED UP TRUCK.

W/O: 70709
Promised Date: 25 MAY 23



Customer #: 47402
BROWN, CHARLES A.



W/O: 70709
Promised Date: 25 MAY 23



Customer #: 47402
BROWN, CHARLES A.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #WALK: 0.00

Job #3 - Internal

Transferred to BAS*70762 on 30 MAY 23

Estimate amount was 0.00

SWAP CAMERA SYSTEM

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

Transferred to BAS*70762 on 30 MAY 23

Estimate amount was 0.00

SWAP ANDERSEN HITCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #4: 0.00

Parts Total: 626.99
Labour Total: 240.00
Sublet Total: 0.00
Extras Total: 159.82
WORK ORDER TOTAL: 1,026.81

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Jun 2023

