

aim : C3420622 Non-Warranty Goodwill Adjustment

Last Modified by:whita

aim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
420622	70720	5/31/2023	5/31/2023	4YDF43036MF811490		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	160.00	0.00	WARR	7/29/20

ny Job	Operation	Description	Svc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7143742L	22-437	Equalizer Jack Pads Rec: RECALL Cause: READ AND FOLLOWED RECALL INSTRUCTIONS. TURNED ON THE LEVELING JACK SYSTEM THEN LOWERED ALL 4 JACKS ABOUT 3 INCHES TO CHECK FOR BOLT TIGHTENED. CHECKED ALL 4 LEVELING JACKS DID NOT FIND ANY LOOSE BOLTS AT THE BOTTOM OF JACK CYLINDERS. RAN JACKS BACK UP. Correction: READ AND FOLLOWED RECALL INSTRUCTIONS. TURNED ON THE LEVELING JACK SYSTEM THEN LOWERED ALL 4 JACKS ABOUT 3 INCHES TO CHECK FOR BOLT TIGHTENED. CHECKED ALL 4 LEVELING JACKS DID NOT FIND ANY LOOSE BOLTS AT THE BOTTOM OF JACK CYLINDERS. RAN JACKS BACK UP.		0.50	0.50	80.00	0.00	1	0.50	Approved

Submitted parts & sublet :	0.00	Approved parts & sublet :	0.00
Submitted labor & sublet :	80.00	Approved labor & sublet :	80.00
Submitted freight :	0.00	Approved freight :	0.00
Tax:	0.00	Tax:	0.00
<b>Total Submitted :</b>	<b>80.00</b>	<b>Total approved :</b>	<b>80.00</b>