



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70720
Promised Date:
20 JUN 23

CUSTOMER WORK ORDER

WO #: 70720 (Appointment Date: 23 MAY 2023 - Time: 07:00am)

Customer: 45685 - ROBERTSON, JOHN
W. - 615-585-9331

Tag:
Author: PH

Location: 0605 BH TO CLOSE THIS

Stock #:
Stock Desc: 2021 5W KEYSTONE
FUZION TOY HAULER 430
Chassis #:
Serial #: 4YDF43036MF811490
Mileage:
Licence:

Invoice #:
Date In: 23 MAY 23
Promised: 30 JUN 23
Date Sched:
Completed: 31 MAY 23
Warr. Date:

Job #1 - Warranty

COMPLAINT: RECALL 23-439 FUEL PUMP CONTROLLER RECALL

CORRECTION: READ AND INSPECTED THE FUEL CONTROLLER. PUT IN PO FOR RECALL PARTS. RECIEVED RECALL PARTS. CUT THE PLASTIC BOX DOWN TO 9 INCHES. REMOVED THE SCREWS THAT HOLD IN THE FUEL CONTROL THEN PUT PLASTIC BOX ON THE BACKAND PUT THE SCREWS BACK IN. HAD TO ADD MORE SCREWS TO HOLD THE PLASTIC BOX. WENT TO THE FRONT OF THE CAMPER TO FIND THE POWER WIRE THAT FEEDS THE FUEL CONTROLLER. DISCONNECTED THE BATTERY AND WIRES TILL THE FUEL CONTROLLER SHUT OFF. FOUND THE RED WIRE THEN CUT IT AND SPLICED IN THE 15 AMP BREAKER. TOOK PICTURES. TIDE WIRE BACK TO CIRCUIT BREAKERS. HOOK BATTERY BACK IN WIRES. SPRAYED EXPANDING FOAM AT THE TOP OF THE PLASTIC BOX SHEILDING THE BACKSIDE OF FUEL CONTROLLER.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	80.00
Z990	MISCELLANEOUS REPAIR	SAR	75.20
Z990	MISCELLANEOUS REPAIR	SAR	4.80

Parts

Part #	Description	Qty	Price	Total
270590	Box - Drain Cover - 7.5" x 12" x 2.7	1.00	3.83	3.83
696343	Fuse - Holder - 15 Amp - 10 Ga - W/P	1.00	2.60	2.60

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JOBS 1&2	1.00	19.53	19.53

Subtotal for Job #1: 185.96

Job #2 - Warranty

COMPLAINT: RECALL 22-437 EQUALIZER JACK PADS RECALL

CORRECTION: READ AND FOLLOWED RECALL INSTRUCTIONS. TURNED ON THE LEVELING JACK SYSTEM THEN LOWERED ALL 4 JACKS ABOUT 3 INCHES TO CHECK FOR BOLT TIGHTENED. CHECKED ALL 4 LEVELING JACKS DID NOT FIND ANY LOOSE BOLTS AT THE BOTTOM OF JACK CYLINDERS. RAN JACKS BACK UP.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	80.00

Customer #: 45685
ROBERTSON, JOHN W.



Subtotal for Job #2: 80.00

W/O: 70720
Promised Date: 30 JUN 23



Job #3 - External

COMPLAINT: Transferred to BAS*70749 on 26 MAY 23
Estimate amount was 0.00
CHECK WATER HEATER, MAY HAVE A LEAK ON THE BACK SIDE

CORRECTION: opened the copartment door then removed customers belongings. removed the panels to get to the backside of the water heater. hooked up city water then made sure the water heater was full. found no leaks with cool water. turned on the gas then fired the water heater to see if the water heater atnk will expand when hot. did see a rust water stain under water heater and inside the foam that surrounds the tank. let water heater run its heat cycle then that when it started to leak. took pictures and put in po for water heater. drained the water out of the water heater.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISCELLANEOUS REPAIR		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - External

IN STORAGE SPOT 83

Subtotal for Job #4: 0.00

Customer #: 45685
ROBERTSON, JOHN W.



Parts Total: 6.43
Labour Total: 240.00
Sublet Total: 0.00
Extras Total: 19.53
WORK ORDER TOTAL: 265.96

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Jun 2023

