

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70757
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 18834 - MARK J. EGLI
Address: 517 STEAMMILL ST. PO BOX 455 NEW HARMONY, IN
47631
Phone: 812-682-2594
Stock Number: 10676 - 2022 CATALINA 243RBSLE 5ZT2CANB2NU039607
VIN: 5ZT2CANB2NU039607 HIN: SER#: 5ZT2CANB2NU039607
Mileage: 0 Work Order Comp: 27 JUN 23
Auth. No: Dealer #:
Warr. Date: 29 APR 22 Work Order Date: 30 MAY 23 Inv #: 393191

WO # Job # Description JOB INFORMATION

70757 1 CUSTOMER HAVING PROBLEMS WITH WALL BOARD in the bathroom CUSTOMER
TALK TO SHARRON
Put notes on jobs seven . Brett completed this job.
Remove toilet. Remove wood box covering water lines. Cut out and
remove wall panels. Remove plastic trim above the walls. Install
two by two's we're needed for panels. Cut out new panels and
install. Staple up new baton strips and putty. Build new box
behind toilet to cover pipes. Silicone around baton strips and
shower stall. Reinstall toilet.

70757 7 In bathroom behind toilet and in between shower and sink wood
trim pieces are expanding
Wallpaper was peeling and wood was expanding
Remove toilet. Remove wood box covering water lines. Cut out and
remove wall panels. Remove plastic trim above the walls. Install
two by two's we're needed for panels. Cut out new panels and
install. Staple up new baton strips and putty. Build new box
behind toilet to cover pipes. Silicone around baton strips and
shower stall. Reinstall toilet.

70757 2 The fake panel near the fridge with the lp detector is missing a
screw and also off center
THE STILE THAT THE PANEL SCREWS INTO IS NOT WIDE ENOUGH.
WENT DOWN TO THEGARAGE AND FOUND A PIECE OF TRIM. CAME BACK TO
SHOP AND CUT TRIM TO LENGTH. APPLIED SUPER GLUE TO BOTTOM AND
SIDE. LET DRY. MOVE PANEL OVER SLIGHTLY AND SECURED WITH SCREWS.

Claim : 70757

 WO # Job # Description JOB INFORMATION

70757 3 Under the refrigerator piece of wood too long marked with blue tape. Also has a rough finish
 cant cut any off of this piece. it holds the fridge in place.
 took a piece of seam tape and placed over rough edge.

70757 4 The knob to the bathroom is offset and has markings on the door
 MOVED DOOR KNOB OVER TO HIDE MARKS.

70757 6 In the master bedroom staples are pulling out areas are marked
 with blue tape
 applied staples to wall. filled holes with putty, cleaned off
 excess with mineral spirits.

 Part No Job# Description PARTS Qty Price Total

F100285215	1	.75X.75 STILE		8.00	0.47	3.76
F100253161	1	TAPE, SEAM VINYL 6" VIPER TRUFFLE		8.00	0.90	7.20
F100130672	7	7/8" BATTEN VIPER TRUFFLE		2.00	1.86	3.72
F100130689	7	SEAM TAPE - PER FT.		12.00	0.15	1.80
F100410661	7	VINYL BOARD, F4E VIPER TRUFFLE 3.6		3.00	48.99	146.97

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	160.00	80.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.50	160.00	240.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.00	160.00	160.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		3.00	160.00	480.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00

 Excode Job# Description EXTRAS Qty Price Total

SS	1	SHOP SUPPLIES		1.00	0.00	0.00
FRT	1	FREIGHT		1.00	45.83	45.83
FRT	7	FRIEGHT		1.00	147.80	147.80

Parts Total: 163.45
 Labour Total: 1,072.00
 Sublet Total: 0.00
 Extras Total: 193.63

>>>> Claim Total: 1,429.08

Customer Signature: _____

Date: _____

Claim : 70757

```
*****
Excode      Job#  Description      EXTRAS      Qty      Price      Total
*****
```