

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 70771  
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC  
Customer: 47402 - CHARLES A. BROWN  
Address: 1700 ROLLETT LANE EVANSVILLE, IN

47712

Phone: 812-457-9375

Stock Number: 11194 - 2022 PARADIGM 310RL 7M5FP362XNA006871

VIN: 7M5FP362XNA006871 HIN:

SER#: 7M5FP362XNA006871

Mileage: 0

Work Order Comp: 15 JUN 23

Auth. No:

Dealer #:

Warr. Date: 25 MAY 23

Work Order Date: 30 MAY 23

Inv #: 392631

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
70771	6	FIND OUT WHY THE SPRAYPORT IS NOT WORKING ON THE DOORSIDE NEAR THE DOOR REMOVE SPRAY PORT AND FOUND CHECK VALVE STUCK IN LINE FITTING STOPING UP LINE TEST SPRAY PORT HAVE NO WATER COMMING OUT, REMOVE SPRAY PORT FROM WALL, DO NOT HAVELINE TO PULLPORT AND FITTING OUT OF WALL, HAVE TO UNLOAD CUSTOMER STUFF FROM COMPARTMENT AND REMOVE ACSESS PANELS TO GET INSIDE TO LINE CUT OFF END AND ADD NEW PICE OF LINE, SWIVEL CONETER AND NEW SPRAY PORT, LEAK TEST FASEN SPRAY PORT TO WALL AND CAP SEAL, PUT ACSESS PANELS BACK AND PUT CUSTOMER STUF BACK UN COMPARTMENT	
70771	2	ONE OF THE KITCKEN DRAWES WILL NOT CLOSE ALL THE WAY IT IS ON THE ISLAND WHEN LOOKING AT THE ISLAND IT IS ON THE TOP RIGHT PULL DRAWES OUT OF CABNET AND FOUND FRAMING FOR DRAW SUPORT NOT FASEND TO CABNET AT THE TOP, only 1 screw in all contions, PULL DRAWES OUT OF CABNET AND FOUND FRAMING FOR DRAW SUPORT NOT FASEND TO CABNET AT THE TOP, only 1 screw in all contions, square up drawer slides to face frame, ad screws to conetions cut supports and add to back of frame, install drawers and test	
70771	3	THE SHOWER WALLS ARE NOT SEALED ON THE BOTTOM AND ARE STICKING OUT AND BOWING OUT pull bottom of shower wall out from wall run silacon along wall push shower wall in to silacone and hold in place with boards untill silacon set up, remove blocking and clean up shower,	

Claim : 70771

```

*****
WO #      Job #   Description          JOB INFORMATION
*****
                close up unit

70771      4      ONE PEICE OF TRIM IS COMING LOOSE IN THE HALL WAY
                find trim simaler and install over door way

70771      7      THE SLIDING BATHROOM DOOR IS NOT FLUSH WITH THE DOOR FRAME
                door 5/8 gap at top and door frame not plumb
                pull off top trim board to get to door adjustment, adjust door so
                top and bottom touching door frame, pull trim strips from door
                frame pull loose fram and shimm frame and nail in place install
                trim strips, fill nail holes,

```

```

*****
Part No    Job#   Description          PARTS          Qty    Price    Total
*****
F100073969  6      Shower - Exterior - Spray Port -    1.00   14.99   14.99
681487     6      1/2" BARB X 1/2 FPT SWIVEL CONE    1.00    3.56    3.56
88-8302    6      BARB UNION                          1.00    5.98    5.98

```

```

*****
Lab Code   Job#   Description          LABOUR          Hrs    Rate    Total
*****
Z990      6      MISC LABOUR CODE (EXTERNAL)         0.50   160.00   80.00
Z990      2      MISC LABOUR CODE (EXTERNAL)         1.00   160.00  160.00
Z990      3      MISC LABOUR CODE (EXTERNAL)         0.00   160.00    0.00
Z990      3      MISC LABOUR CODE (EXTERNAL)         0.50   160.00   80.00
Z990      4      MISC LABOUR CODE (EXTERNAL)         0.20   160.00   32.00
Z990      7      MISC LABOUR CODE (EXTERNAL)         0.00   160.00    0.00
Z990      7      MISC LABOUR CODE (EXTERNAL)         0.70   160.00  112.00

```

Parts Total: 24.53  
Labour Total: 464.00  
Sublet Total: 0.00  
Extras Total: 0.00

>>>> Claim Total: 488.53

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_