



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70771
Promised Date:
24 MAY 23

CUSTOMER WORK ORDER

WO #: 70771

Customer: 47402 - BROWN, CHARLES
A. - 812-457-9375
Tag:
Author: BH
Location: 0625 CHECK WORK

Stock #: 11194
Stock Desc: 2022 5W ALLIANCE RV
PARADIGM 310RL
Chassis #: 7M5FP362XNA006871
Serial #: 7M5FP362XNA006871
Mileage: 0
Licence:

Invoice #:
Date In: 30 MAY 23
Promised: 31 MAY 23
Date Sched:
Completed: 15 JUN 23
Warr. Date: 25 MAY 23

Job #1 - Internal

COMPLAINT: UNIT HAS A HYDRILK LEAK ABOUT THE MIDDLE OF THE UNIT CUSTOMER WOULD LIKE TO HAVE THE UNDER BELLY REPLACED

CORRECTION: BRING UNIT IN AND PULL UNDERBELLY DOWN, (NAILS SHOT IN TO FRAME) DO NOT FIND ANY OIL ON UNDER BELLY, CHECK FOR LEACK ON HYDRLIC LINES, NO LEAKS FOUND, LET UNIT STAND ON OVER EXTENDED JACKS IN BAY AND SIT OVER NIGHT NO OIL LEAK FOUND PUT UNDER BELLY BACK UP (TECK SCREW DO NOT WANT TO DRILL THROUGH FRAME HAVE TO DRILL HOLES FOR SCREWS)

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: ONE OF THE KITCKEN DRAWES WILL NOT CLOSE ALL THE WAY IT IS ON THE ISLAND WHEN LOOKING AT THE ISLAND IT IS ON THE TOP RIGHT

CAUSE: PULL DRAWAS OUT OF CABNET AND FOUND FRAMING FOR DRAW,SUPORT NOT FASEND TO CABNET AT THE TOP, only 1 screw in all contions,

CORRECTION: PULL DRAWAS OUT OF CABNET AND FOUND FRAMING FOR DRAW SUPORT NOT FASEND TO CABNET AT THE TOP, only 1 screw in all contions, square up drawer slides to face frame, ad screws to conetions cut supports and add to back of frame, install drawers and test

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	160.00

Subtotal for Job #2: 160.00

Job #3 - Warranty

COMPLAINT: THE SHOWER WALLS ARE NOT SEALED ON THE BOTTOM AND ARE STICKING OUT AND BOWING OUT

CORRECTION: pull bottom of shower wall out from wall run silacon along wall push shower wall in to silacon and hold in place with boards untill silacon set up,

Customer #: 47402
BROWN, CHARLES A.



remove blocking and clean up shower, close up unit

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00
Subtotal for Job #3:			80.00

Job #4 - Warranty

COMPLAINT: ONE PEICE OF TRIM IS COMING LOOSE IN THE HALL WAY

CORRECTION: find trim simaler and install over door way

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	32.00
Subtotal for Job #4:			32.00

Job #5 - Internal

COMPLAINT: HOOK UP THE ICE MAKER

CORRECTION: unload cabnet remove access panel, found ice maker line taped to refer 120 vac cord, try to conet up will not seal with out line insert for plastic lin turn in po install insert and contup line test for water leak

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
8103	ICE MAKER INSTALL KIT	1.00	N/C	N/C
Subtotal for Job #5:				0.00

Job #6 - Warranty

COMPLAINT: FIND OUT WHY THE SPRAYPORT IS NOT WORKING ON THE DOORSIDE NEAR THE DOOR

CAUSE: REMOVE SPRAY PORT AND FOUND CHECK VALVE STUCK IN LINE FITTING STOPING UP LINE

CORRECTION: TEST SPRAY PORT HAVE NO WATER COMMING OUT, REMOVE SPRAY PORT FROM WALL, DO NOT HAVELINE TO PULLPORT AND FITTING OUT OF WALL, HAVE TO UNLOAD CUSTOMER STUFF FROM COMPARTMENT AND REMOVE ACSESS PANELS TO GET INSIDE TO LINE CUT OFF END AND ADD NEW PICE OF LINE, SWIVEL CONETER AND NEW SPRAY PORT, LEAK TEST FASEN SPRAY PORT TO WALL AND CAP SEAL, PUT ACSESS PANELS BACK AND PUT CUSTOMER STUF BACK UN COMPARTMENT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00

Parts

Part #	Description	Qty	Price	Total
416120	Shower - Exterior - Spray Port - W/B	1.00	14.99	14.99
681487	1/2" BARB X 1/2 FPT SWIVEL CONE	1.00	3.56	3.56
88-8302	BARB UNION	1.00	5.98	5.98

W/O: 70771
Promised Date: 31 MAY 23



Customer #: 47402
BROWN, CHARLES A.



Subtotal for Job #6: 104.53

Job #7 - Warranty

COMPLAINT: THE SLIDING BATHROOM DOOR IS NOT FLUSH WITH THE DOOR FRAME

CAUSE: door 5/8 gap at top and door frame not plumb

CORRECTION: pull off top trim board to get to door adjustment, adjust door so top and bottom touching door frame, pull trim strips from door frame pull loose fram and shimm frame and nail in place install trim strips, fill nail holes,

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	112.00

Subtotal for Job #7: 112.00

Job #8 - Internal

COMPLAINT: LOOK AT BOTH FENDERS THE COLOR IS FADED FROM THE MAXXGAURD SEE IF WE CAN CLEAN OR ORDER NEW ONES

CAUSE: INSTALL NEW FENDERS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
10271	FENDERSKIRT - TANDEM -BLACK	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - FENDERS	1.00	N/C	N/C

Subtotal for Job #8: 0.00

Parts Total: 24.53
Labour Total: 464.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 488.53

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Jun 2023

W/O: 70771
Promised Date: 31 MAY 23

Customer #: 47402
BROWN, CHARLES A.

