

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1556092
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAWB2PX028798
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT313RLTSLE
		DEALER RO #	70774
		CLAIM START DATE	06/05/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	24-30-100-001049	Operational Description
		Cabinet End Panel - Repair/Interior/Cabinetry
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-06-05 10:25:37 :: FIX OVERHEAD RANGE FIX OVERHEAD RANGE HOOD. Rattached panel under cabinet that range hood is mounted to. Added screws to secure panel to bottom of cabinet frame.		
Model #	Dlr Sub Hrs	0.20
Serial #	Appr Hrs	0.10
	Sub Labor Amt	\$32.00
	Appr Labor Amt	\$16.00
Notes		
EXCESSIVE AMOUNT REQUESTED		
CHANGED TO SIMILAR REPAIR TIME		

Labor

Line# 2

Operation Code	10-11-24-00-000207	Operational Description
		Slide Out Corner Block - Frame & Chassis/Slide Out System-Seals/Repair/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-06-05 10:26:37 :: WHEN THE SLIDE IS OUT YOU CAN SEE LIGHT FROM OUTSIDE WHEN THE SLIDE IS OUT YOU CAN SEE LIGHT FROM OUTSIDE. Foam blocks are not covering gap between slideout and wall frame. Removed foam blocks. Trimmed foam blocks to fit. Applied glue to foam blocks and Remounted to cover gap.		
Model #	Dlr Sub Hrs	0.40
Serial #	Appr Hrs	0.20
	Sub Labor Amt	\$64.00
	Appr Labor Amt	\$32.00
Notes		
EXCESSIVE AMOUNT REQUESTED		
CHANGED TO FLAT RATE X2		

Labor

Line# 3

Operation Code	24-30-98-000996	Operational Description
		Bed Structure - Repair/Interior/Beds, Mattress
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-06-05 10:27:26 :: MAIN BED FRAME BUSTED OUT ON LEFT CORNER MAIN BED FRAME BUSTED OUT ON LEFT CORNER. Screw came loose allowing side frame to move out. Removed factory installed screw. Moved side frame back into correct position. Secured with (3) new screws to hold side frame in correct position.		
Model #	Dlr Sub Hrs	0.50
Serial #	Appr Hrs	0.25
	Sub Labor Amt	\$80.00
	Appr Labor Amt	\$40.00
Notes		

EXCESSIVE AMOUNT REQUESTED
CHANGED TO SIMILAR REPAIR TIME

Submitted

Labor Amt	\$176.00
Parts & Freight	\$0.00
Total	\$176.00

Approved

Labor Amt	\$88.00
Parts & Freight	\$0.00
Total	\$88.00

DEALER**DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER**DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.