



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70774
Promised Date:
40 JUN 23

CUSTOMER WORK ORDER

WO #: 70774

Customer: 10245 - PRICE, CHAD T. -
618-263-7854

Tag:

Author: BH

Location: 0610 CHECK PREAUTH

Stock #: 10871

Stock Desc: 2023 TT COACHMEN

CATALINA 313RLTSLE

Chassis #: 5ZT2CAWB2PX028798

Serial #: 5ZT2CAWB2PX028798

Mileage:

Licence:

Invoice #:

Date In: 31 MAY 23

Promised: 10 JUN 23

Date Sched:

Completed: 07 JUN 23

Warr. Date: 30 MAY 23

Job #FPDINTT - Internal

COMPLAINT: Transferred to BAS*70838 on 05 JUN 23

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT - FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Installed new battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Recorded all tire serial numbers. Checked roof and both awnings. Checked all interior lights. Checked both Air Conditioners. Checked all appliances. Added water to fresh water tank and flushed water pump. Connected to city water and flushed water lines and faucets, including washer faucets. Opened by-pass on water heater and filled. Purged all air from water system. Performed LP drop test and set LP pressure at 11 in.wc. Checked water heater on LP and Electric. Checked Fireplace and Radio. Test TV not picking up channels inside shop. Will have to move unit outside shop. Moved unit out of shop. Checked TV antenna on all TV locations. Moved unit to wash bay area.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

COMPLAINT: Transferred to BAS*70838 on 05 JUN 23

Estimate amount was 0.00

SWAP CUSTOMER'S HITCHWORK

CAUSE: PREBILLED TO ZACH TO RO 70837

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Internal

Transferred to BAS*70838 on 05 JUN 23

Estimate amount was 0.00

SWAP TV AND BRACKET AND PUT IN NEW CAMPER ABOVE FIREPLACE

Labor



Customer #: 10245
PRICE, CHAD T.

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: FIX OVERHEAD RANGE

CAUSE: FIX OVERHEAD RANGE HOOD.

CORRECTION: Rattached panel under cabinet that range hood is mounted to. Added screws to secure panel to bottom of cabinet frame.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	16.00

Subtotal for Job #2: 16.00

Job #3 - Warranty

COMPLAINT: WHEN THE SLIDE IS OUT YOU CAN SEE LIGHT FROM OUTSIDE

CAUSE: WHEN THE SLIDE IS OUT YOU CAN SEE LIGHT FROM OUTSIDE.

CORRECTION: Foam blocks are not covering gap between slideout and wall frame. Removed foam blocks. Trimmed foam blocks to fit. Applied glue to foam blocks and Remounted to cover gap.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00

Subtotal for Job #3: 32.00

Job #4 - Warranty

COMPLAINT: MAIN BED FRAME BUSTED OUT ON LEFT CORNER

CAUSE: MAIN BED FRAME BUSTED OUT ON LEFT CORNER.

CORRECTION: Screw came loose allowing side frame to move out. Removed factory installed screw. Moved side frame back into correct position. Secured with (3) new screws to hold side frame in correct position.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	40.00

Subtotal for Job #4: 40.00

Job #5 - Warranty

Transferred to BAS*70838 on 05 JUN 23

Estimate amount was 0.00

SEE BEN OR DREW

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 88.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 88.00

W/O: 70774
Promised Date: 10 JUN 23



Customer #: 10245
PRICE, CHAD T.

