

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 1560185
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 4X4TCKC25NX158985
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 017 / 017A
ITEM # ACKT274BRB
DEALER RO # 70866
CLAIM START DATE 06/07/2023
CLAIM END DATE 01/01/1900

Labor rate: \$160.00

OWNER INFORMATION

JAY GODSEY
6809 N HAPPE RD
Evansville, IN 47720
USA

Retail Date of Purchase 06/06/2023

WARRANTY EXPIRATION DATE 06/06/2024

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	70-187-01-00-002240	Coleman AC Shroud - Appliances/Roof AC (Coleman-RVP)/Replace/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-06-07 12:34:14 :: AC UNIT INSIDE PLENUM BLOWING DOWN INSIDE AC UNIT INSIDE PLENIUM BLOWING DOWN INSIDE. Removed ceiling plenum. Found that inside plenum was mounted with wrong side down. This allowed air return divider to shift and cause discharge and return air to mix. Both ceiling plenums are broken. Also ducts need to be retaped to seal properly. Retaped around ducts. Installed new inside and ceiling plenum.		
	Model # NA	Dlr Sub Hrs 1.00
	Serial # NA	Appr Hrs 0.75
		Sub Labor Amt \$160.00
		Appr Labor Amt \$120.00
Notes		
repair		

Submitted	Labor Amt	\$160.00
	Parts & Freight	\$0.00
	Total	\$160.00

Approved	Labor Amt	\$120.00
	Parts & Freight	\$0.00
	Total	\$120.00

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.