

6/30/20
03:29:22

Approved date 6/29/2023

4YDFHMU20NA74297C

Complaint: THERE IS A LEAK IN THE SLIDE ROOM IN THE FRIDGE AND DINNETE SLIDE REAR WINDOW IS LEAKING Cause: leaking window.
Correction: REMOVE VALANCE AND BLIND. REMOVE WINDOW. REMOVE WALL PANEL AND BATON STRIP. CHECK STUDS FOR WATER DAMAGE. PUT NEW WALL PANEL BACK WITH NEW BATON STRIP. ROUTER OUT PANEL. PUT BACK WINDOW AND BLIND.

KRV – Labor time approved in accordance with Keystone RV's flat rate manual.

KRV – Labor time adjusted allowing for proper repair procedure to be performed.

KRV- adjusted time 6/29 added 2.0 hrs. for laminated wall panel replacement

Qty	Hours	Sub operation	Description
1	1.50	2102115B	Wall - Laminated Interior Wall Pane
6.00			

paper claims only use one pre-authorization number per warranty claim for

1. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the