



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70873
Promised Date:
20 JUN 23



Customer #: 1000
BASDEN'S AMERICAN RV,

CUSTOMER WORK ORDER

WO #: 70873

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0630 CHECK PREAUTH

Stock #: 11168
Stock Desc: 2022 5W KEYSTONE
MONTANA HIGH COUNTRY 377FL
Chassis #: 4YDFHMU20NA742970
Serial #: 4YDFHMU20NA742970
Mileage: 0
Licence:

Invoice #:
Date In: 07 JUN 23
Promised: 30 JUN 23
Date Sched:
Completed: 30 JUN 23
Warr. Date:

Job #1 - Warranty

COMPLAINT: THERE IS A LEAK IN THE SLIDE ROOM IN THE FRIDGE AND DINNETE SLIDE REAR WINDOW IS LEAKING

CAUSE: Water damage to side wall and backwall of slide room.

CORRECTION: Remove the valance and blinds .Remove both windows. Cut over thirty two inches on sidewall and remove panel. Remove nails and glue. Remove wet installation. Put blocking in wall were needed. Cut over sixteen inches on rear wall. Remove panel. Remove nails and glue. . Cut and glue back new wallboards. Router out windows. Clean off windows and put putty tape on. Put windows back in. Put baton strips on and putty .Put blinds back up and put the valances back. Silicone windows.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	193.60
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	BB	155.20
Z990	MISCELLANEOUS REPAIR	BB	611.20

Parts

Part #	Description	Qty	Price	Total
651637	Seam - Tape - 1" - Burlap Shale - 4 Mil - Xtina 36	10.00	0.22	2.20
640069	Panel - 3.6mm x 48" x 108" - Carb 2	1.00	62.95	62.95
636349	Trim - Batten - 3.0mm x 7/8" x 96" -	2.00	2.54	5.08
1578392	LIQUID NAILS XTREME HD 100Z.	2.00	7.58	15.16
4773	R11 ROLLED INSULATION	1.00	45.99	45.99
500627	CLEAR SIKASIL PLUS	1.00	16.59	16.59

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-TAPE	1.00	16.69	16.69
FRT	FREIGHT-TRIM AND PANEL	1.00	142.31	142.31

Subtotal for Job #1: 1,266.97

Job #2 - Internal

COMPLAINT: CLEAN THE BIRDS NEST OUT OF CAMPER

CORRECTION: THERE WAS BIRDS NEST IN 2 AREAS IN UNDER BELLY. FIRST ONE WAS IN THE REAR LEFT CORNER. I TOOK DOWN METAL SKIRTING BY BUMPER AND REMOVED A LARGE BIRDS NEST. I BLEW OUT THE UNDER BELLY TO REMOVE THE REST OF THE NEST. THE SECOND ONE WAS AT THE SLIDE ROOM RAM AGAIN. I CUT THE UNDERBELLY AND REMOVED NEST, I BLEW THAT AREA OUT AS WELL. I CUT A SHEET OF PANNELING TO REINFORCE THE PATCH. I CUT IT LARGER THAT THE OPENING AND SCREWED UNDER BELLYTO IT THEN SCREWEDE THE



FLAP I HAD CUT. I GOT SOME RUBBER SEAL AND COVERED THE HOLE FOR THE SLIDE RAM.
CLEANED UP MY MESS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #2: 0.00

Parts Total: 147.97
Labour Total: 960.00
Sublet Total: 0.00
Extras Total: 159.00
WORK ORDER TOTAL: 1,266.97

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Jun 2023

W/O: 70873
Promised Date: 30 JUN 23



Customer #: 1000
BASDEN'S AMERICAN RV,

