

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1605586
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKT27PK085831
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT18RRBL-94
CARL E LYELL		DEALER RO #	70878
801 B INDEOENDENCE DR		CLAIM START DATE	07/15/2023
Madisonville, KY 42431		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/10/2023	WARRANTY EXPIRATION DATE	06/10/2024

Claim Line Details

Labor

Line# 1	Operation Code 40-106-01-00-001254 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-07-15 13:45:57 :: THE ROAD SIDE EXTERIOR LIGHT SWITCH IS NOT FUNCTIONING GOOD POWER AND GROUND LIGHT NOT WORKING GET NEW LIGHT AND REPLACE	Operational Description Scare Light - Electrical/12 Volt Exterior/Replace/No Tread Code
	Model # Serial #	Dlr Sub Hrs Appr Hrs
		0.20 0.20
		Sub Labor Amt Appr Labor Amt
		\$32.00 \$32.00
	Notes	

Labor

Line# 2	Operation Code 70-656-01-00-003977 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-07-15 13:47:52 :: PLENUM IS INSTALLED WRONG FROM FACOTRY INSTALLED A DUCTED AND IT SHOULD BE A NON DUCTED FOUND NO AIR DUCTS	Operational Description Top Cover or Shroud - Appliances/Roof AC (Furrion)/Replace/No Tread Code
	Model # Serial #	Dlr Sub Hrs Appr Hrs
	NA NA	0.80 0.80
		Sub Labor Amt Appr Labor Amt
		\$128.00 \$128.00
	Notes	

Please attach photos showing the AC interior shroud.

Thank you!

Denied. That is the correct AC shroud.

Submitted

Labor Amt	\$160.00
Parts & Freight	\$0.00
Total	\$160.00

Approved

Labor Amt	\$160.00
Parts & Freight	\$0.00
Total	\$160.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.