



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70921
Promised Date:
20 JUN 23



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 70921

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0706 CHECK PREAUTH

Stock #: 10898
Stock Desc: 2023 5W KEYSTONE
COUGAR HALF-TON 29RLI
Chassis #: 4YDFCGN2XP2508802
Serial #: 4YDFCGN2XP2508802
Mileage: 0
Licence:

Invoice #:
Date In: 13 JUN 23
Promised: 30 JUN 23
Date Sched:
Completed: 30 JUN 23
Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: PDI for new fifth wheel.

CORRECTION: The outside furnace cover Was not screwed in all the way. I got longer screws and put them in, and it's Sendto help it. There was no cable reception in the bedroom or outside area. I checked the receptacles.

Check The Wire linked inside of the coax kept looking for the problem. I found the problem was in the outside. Main cable bank, the orange wire. And the Gray wire on the coax was both loose from the bank. The orange wire fed the outside TV. The Gray wire fed the inside TV. There was trim that was falling down in the kitchen. I stapled it back up. Up the blind above the low seat would not stay down. I had to adjust the rollers on Thon both sides to tighten it up.

The front door casing was bent. From delivery inspection notes, I fixed the doorcasing the latch on the large compartment door on the front right side would not was sdicking. I I repaired the damaged area at the island that was found in the delivery inspection. I removed the blackmark on the door found at delivery inspection. I also helped Sean with removing and installing a fresh water tank that was in his Bay. I took the fifth wheel back out on the lot and set the slide out.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DWW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DWW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DWW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DWW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR FRAMEW IS BENT

CORRECTION: I REPAIRED THIS ON THE PDI. I DIDNT KNOW BEN ADDED A LINE FOR THE DOOR FRAME. I WILL ADD THIS TO MY NOTES.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	32.00





Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: OUT SIDE FURANCE COVER NOT INSTALLED ALL THE WAY

CORRECTION: I got longer screws and put them in,

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	1.75

Subtotal for Job #2: 1.75

Job #3 - Warranty

COMPLAINT: There was no cable reception in the bedroom or outside area.

CORRECTION: Check The Wire linked inside of the coax kept looking for the problem. I found the problem was in the outside. Main cable bank, the orange wire. And the Gray wire on the coax was both loose from the bank. The orange wire fed the outside TV. The Gray wire fed the inside TV.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	5.25

Subtotal for Job #3: 5.25

Job #4 - Warranty

COMPLAINT: There was trim that was falling down in the kitche

CORRECTION: STAPLED IT BACK UP

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	1.75

Subtotal for Job #4: 1.75

Job #5 - Warranty

COMPLAINT: Up the blind above the low seat would not stay down.

CORRECTION: I had to adjust the rollers on Ton both sides to tighten it up.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	1.75

Subtotal for Job #5: 1.75

Parts Total: 0.00
 Labour Total: 42.50
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 42.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

