

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	1591444
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	5ZT2CAEC7PK006058
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$160.00	<b>SITE/WAREHOUSE</b>	203 / 203
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	BCAT164BHX
KIMBER M YOUNG		<b>DEALER RO #</b>	71035
202 GREEN VALLEY RD		<b>CLAIM START DATE</b>	07/03/2023
Chandler, IN 47610		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	06/30/2023	<b>WARRANTY EXPIRATION DATE</b>	06/30/2024

## Claim Line Details

### Labor

**Line# 1**      **Operation Code**      **Operational Description**  
 32-640-00-01-001096      Interior Trim or Moldings, each - Cargo Interior/Door, Wall, Ceiling, Molding/No Tread Code/Replace

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2023-07-03 17:31:03 :: FRIDGE IS NOT SECURE TO THE CUT OUT Removed trim around fridge. Se used s rew into floor. Secured trim.

<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.40	<b>Sub Labor Amt</b>	\$64.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b>	\$48.00

**Notes**  
 EXCESSIVE AMOUNT REQUESTED  
 CHANGED TO SIMILAR REPAIR TIME

### Labor

**Line# 2**      **Operation Code**      **Operational Description**  
 61-586-01-001484      Fresh Water Fill Hose - Marine Plumbing/Plumbing/Replace

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2023-07-03 17:33:36 :: FRESH TANK FILL LINE IS RUNNING UP HILL AND WONT ALLOW WATER TO FILL TANK Fill hose is crushed. The hole that was cut from the factory is about 2-3inches off. Fill line is pinched in between floor and fitting. Removed panel from under couch. Found where hose goes through floor. Took multi tool and cut around hose. Removed excess wood. Pulled hose out from floor. Checked for damages on hose. Filled fresh tank to rest. Cleaned up mess.

<b>Model #</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$160.00
<b>Serial #</b>	<b>Appr Hrs</b>	1.00	<b>Appr Labor Amt</b>	\$160.00

**Notes**  
 AUTHORIZED AS REQUESTED

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 30-102-12-00-002691      Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2023-07-03 17:35:30 :: WALL PANEL IN BATHROOM COMING LOOSE FROM WALL Wall panel is not secure in bathroom. Secured with staples.

<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b>	\$80.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b>	\$80.00

**Notes**  
 AUTHORIZED AS REQUESTED

<b>Submitted</b>	Labor Amt	\$304.00
	Parts & Freight	\$0.00
	Total	\$304.00

<b>Approved</b>	Labor Amt	\$288.00
	Parts & Freight	\$0.00
	Total	\$288.00

---

<b>DEALER</b>	<b>DATE</b>
<b>SIGNATURE</b>	

I certify that I have performed these repairs consistent with Forest River Policies.

---

<b>CUSTOMER</b>	<b>DATE</b>
<b>SIGNATURE</b>	

All repairs described have been inspected and are satisfactory.