

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71062
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11121 - 2023 CHEROKEE 304BH 4X4TCKF25RX162004
VIN: 4X4TCKF25RX162004 HIN: SER#: 4X4TCKF25RX162004
Mileage: 0 Work Order Comp: 31 AUG 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 29 JUN 23 Inv #: 396184

WO # Job # Description JOB INFORMATION

71062 4 FRESH TANK IS LEAKING WATER FROM UNDERBELLY
water comming from underbelly as filling freash tank,
water comming from underbelly as filling freash tank, pull down
underbelly at tank, found spin welds on tank leaking needs new
tank REMOVE FROUNT JACKS TO DROP UNDER BELLY, REMOVE DRAIN VALVE
TO DROP UNDER BELLY , PULL UNDER BELLY DOWN ONLY FOUND NO #s ON
TANK THEWAY MOUNTED, GET SIZE OF TANK, AND MAKE PO, TANK HAS TANK
HEATER Close up unit and pull out to service lot BRING UNIT IN
AND PULL DOWN UNDERBELLY, REMOVE TANK TRY TO REMOVE TANK HEATER
BUT IT CAME APART, TURN IN PO FOR TANK HEATER, FASEN UNDER BELLY
UP AND PULL OUT TO SEVICE LOT BRING UNIT BACK IN AND INSTALL NEW
TANK AND CONET UP LINES AND WIRES, WATER TEST FOR LEAKS, OUT
UNDER BELLY BACK UP PULL OUT TO LOT

71062 5 LIGHT OVER STOVE DOES NOT WORK
LIGHT OVER STOVEDOSE NOT COME ON
LIGHT OVER STOVE DOSE NOT COME ON REMOVE LENSAND PULL LIGHT DOWN
TO GET #s FOUND LENS HAS A LIGHT BUTTON THAT WILL NIT MOVE, TURN
PO

71062 6 SLIDE ROOM FACIA IS MISCUT ALLOWING DAYLIGHT TO BE SEEN AT THE
BOTTOM
SLIDE ROOM FACEUHA HAS OVER SIZE CUTS WITH SPACE SHOWING SEALS
AND DRAIN FOR SLIDE ROOM
BY REPLACING FACEUHA BOARDS CUT TO FIT WILL COVER SPACETURN PO

Claim : 71062

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
71062      7      THE QUICK DROP STABILIZER JACK IS NOT DROPPING ALL THE WAY.
               QUICK DROP LEG DOSE NOT DROP ALL THE WAY LEG MAY BE BENT NEEDS
               NEW LEG
               RAIS FRONT OF UNIT TO GET UNDER TO DROP UNDER BELLY, DROP LEGS TO
               SUPORT JACK AS SCREWS ARE REMOVED 1 SIDE LEG DOSE NOT DROP ALL
               THE WAY, JACK LEG ONLY DROPS 3 HOLES IN LEG, JACK IS UNDER FREASH
               TANK AND UNDER BELLY HAS TO BE REMOVED TO GET TO TANK

71062      1      NO TV SIGNAL IN BEDROOM OR OUTSIDE PORT
               NO TV SIGNAL IN BEDROOM AND OUTSIDE
               REMOVE BOOSTER FROM CEILING AND FOUND LOOSE WIRES FROM BAB MADE
               CONNETTIONS ON WIRE ENDS REPLACE ENDS AND GET TVSIGNAL IN
               BEDROOM, TEST OUT SIDE AFTER REPLAING BOTH ENDS OF WIRE, TESTER
               SHOWS WIRE SHORTED, WILL NEED TO RUN NEW WIRE THROUGH CEILING AND
               WALL TO OUT SIDE PORT, REMOVE ELETRIC RECEPICAL IN CEILING AND
               FISH WIRES OUT HOLE TRACE WIRE CUT AND SPLICE IN A SETION OF NEW
               WIRE AND TEST FOR TV SIGNAL AT OUT SIDE PORT, TEST GOOD, MOUNT
               ALL PORTS AND CAPSEAL OUT SIDE PORT

71062      2      FRIDGE DOOR IS NOT LATCHING AND GASKET IS NOT SEALING
               refer compartment is freezing up over weekend doors not linning
               up with latch
               remove latch from refer and mark door latch, install latch,
               remove doors and find washers to raise door for latch, install
               washers and doors test, refer door has 2 platic washers and 1
               steel to get to hith, freezer door has 1 steel washer, test,
               clean ice and water out of refer and freezer

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
F100257740    4      TANK, FRESH WATER W/ PROBES, 40 G  1.00      100.04      100.04
40E04495A     4      TANK HEAT PAD 108794                1.00       28.75       28.75
40E15514A     5      LIGHT, 4 1/2" LED PUCK LIGHT WITH  1.00        1.87        1.87
F100419070    6      FASCIA, 5/8" X 6" X 108" HEADER -  2.00       10.76       21.52
F100374939    7      JACK, 68.5" CENTER QUICK DROP STA  1.00       94.88       94.88

```

```

*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.00     160.00        0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.41     160.00       65.60
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.59     160.00       94.40
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.00     160.00        0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.00     160.00        0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.00     160.00        0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.00     160.00        0.00

```

Claim : 71062

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      2.00     160.00     320.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.19     160.00     30.40
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.01     160.00      1.60
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.50     160.00     80.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.89     160.00    142.40
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.11     160.00     17.60
Z990      1    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      1    MISC LABOUR CODE (EXTERNAL)      1.00     160.00    160.00
Z990      1    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.10     160.00     16.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT       4    FREIGHT - JOBS 4,5,6,7      1.00     190.00    190.00
FRT       4    UPS-TANK HEATER PAD        1.00      17.27     17.27

```

```

Parts Total:      247.06
Labour Total:     928.00
Sublet Total:       0.00
Extras Total:     207.27

```

>>>> Claim Total: 1,382.33

Customer Signature: _____

Date: _____