



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71062
Promised Date:
90 1111 92



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 71062

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0909 SEE IF JAMES HAS
COMPLETED THIS YET

Stock #: 11121
Stock Desc: 2023 TT FOREST RIVER
CHEROKEE 304BH
Chassis #: 4X4TCKF25RX162004
Serial #: 4X4TCKF25RX162004
Mileage: 0
Licence:

Invoice #:
Date In: 29 JUN 23
Promised: 29 JUL 23
Date Sched:
Completed: 31 AUG 23
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*71125 on 10 JUL 23
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LP20	20 LB. LP CYLINDER	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: NO TV SIGNAL IN BEDROOM OR OUTSIDE PORT

CAUSE: NO TV SIGNAL IN BEDROOM AND OUTSIDE

CORRECTION: REMOVE BOOSTER FROM CEILING AND FOUND LOOSE WIRES FROM BAB MADE CONNETTIONS ON WIRE ENDS REPLACE ENDS AND GET TVSIGNAL IN BEDROOM, TEST OUT SIDE AFTER REPLAING BOTH ENDS OF WIRE, TESTER SHOWS WIRE SHORTED, WILL NEED TO RUN NEW WIRE THROUGH CEILING AND WALL TO OUT SIDE PORT, REMOVE ELETRIC RECEPICAL IN CEILING AND FISH WIRES OUT HOLE TRACE WIRE CUT AND SPLICE IN A SETION OF NEW WIRE AND TEST FOR TV SIGNAL AT OUT SIDE PORT, TEST GOOD, MOUNT ALL PORTS AND CAPSEAL OUT SIDE PORT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00



Subtotal for Job #1: 160.00

Job #2 - Warranty

COMPLAINT: FRIDGE DOOR IS NOT LATCHING AND GASKET IS NOT SEALING

CAUSE: refer compartment is freezing up over weekend doors not latching up with latch

CORRECTION: remove latch from refer and mark door latch, install latch, remove doors and find washers to raise door for latch, install washers and doors test, refer door has 2 plastic washers and 1 steel to get to hith, freezer door has 1 steel washer, test, clean ice and water out of refer and freezer

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	16.00

Subtotal for Job #2: 16.00

Job #3 - Warranty

COMPLAINT: FRESH TANK IS NOT REGISTERING ON MONITOR BOARD

CAUSE: AFTER PULLING DOWN UNDER BELLY TO FIND LEAK FOUND GROUND WIRE SPIN WELD LEAKING AND WIRE LOOSE

CORRECTION: WILL BE FIXED WHEN NEW TANK IS INSTALLED

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: FRESH TANK IS LEAKING WATER FROM UNDERBELLY

CAUSE: water coming from underbelly as filling fresh tank,

CORRECTION: water coming from underbelly as filling fresh tank, pull down underbelly at tank, found spin welds on tank leaking needs new tank

REMOVE FRONT JACKS TO DROP UNDER BELLY, REMOVE DRAIN VALVE TO DROP UNDER BELLY, PULL UNDER BELLY DOWN ONLY FOUND NO #s ON TANK THEWAY MOUNTED, GET SIZE OF TANK, AND MAKE PO, TANK HAS TANK HEATER

Close up unit and pull out to service lot

BRING UNIT IN AND PULL DOWN UNDERBELLY, REMOVE TANK TRY TO REMOVE TANK HEATER BUT IT CAME APART, TURN IN PO FOR TANK HEATER, FASEN UNDER BELLY UP AND PULL OUT TO SERVICE LOT

BRING UNIT BACK IN AND INSTALL NEW TANK AND CONET UP LINES AND WIRES, WATER TEST FOR LEAKS, OUT UNDER BELLY BACK UP PULL OUT TO LOT

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	65.60
Z990	MISC LABOUR CODE (EXTERNAL)	JP	94.40
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	320.00





Parts

Part #	Description	Qty	Price	Total
F100257740	TANK, FRESH WATER W/ PROBES, 40 GAL	1.00	100.04	100.04
40E04495A	TANK HEAT PAD 108794	1.00	28.75	28.75

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - JOBS 4,5,6,7	1.00	190.00	190.00
FRT	UPS-TANK HEATER PAD	1.00	17.27	17.27

Subtotal for Job #4: 816.06

Job #5 - Warranty

COMPLAINT: LIGHT OVER STOVE DOES NOT WORK

CAUSE: LIGHT OVER STOVE DOES NOT COME ON

CORRECTION: LIGHT OVER STOVE DOES NOT COME ON REMOVE LENS AND PULL LIGHT DOWN TO GET #s FOUND LENS HAS A LIGHT BUTTON THAT WILL NOT MOVE, TURN PO

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	30.40
Z990	MISC LABOUR CODE (EXTERNAL)	JP	1.60

Parts

Part #	Description	Qty	Price	Total
5221	LIGHT, 4 1/2" LED PUCK LIGHT WITH SW	1.00	1.87	1.87

Subtotal for Job #5: 33.87

Job #6 - Warranty

COMPLAINT: SLIDE ROOM FACIA IS MIS-CUT ALLOWING DAYLIGHT TO BE SEEN AT THE BOTTOM

CAUSE: SLIDE ROOM FACEUHA HAS OVER SIZE CUTS WITH SPACE SHOWING SEALS AND DRAIN FOR SLIDE ROOM

CORRECTION: BY REPLACING FACEUHA BOARDS CUT TO FIT WILL COVER SPACE TURN PO

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00

Parts

Part #	Description	Qty	Price	Total
F100419070	FASCIA, 5/8" X 6" X 108" HEADER - HA	2.00	10.76	21.52

Subtotal for Job #6: 101.52

Job #7 - Warranty

COMPLAINT: THE QUICK DROP STABILIZER JACK IS NOT DROPPING ALL THE WAY.

CAUSE: QUICK DROP LEG DOES NOT DROP ALL THE WAY LEG MAY BE BENT NEEDS NEW LEG

CORRECTION: RAISE FRONT OF UNIT TO GET UNDER TO DROP UNDER BELLY, DROP LEGS TO SUPPORT JACK AS SCREWS ARE REMOVED 1 SIDE LEG DOES NOT DROP ALL THE WAY, JACK LEG ONLY DROPS 3 HOLES IN LEG, JACK IS UNDER FRESH TANK AND UNDER BELLY HAS TO BE REMOVED TO GET TO TANK

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990	MISC LABOUR CODE (EXTERNAL)	JP	142.40
Z990	MISC LABOUR CODE (EXTERNAL)	JP	17.60

Parts				
Part #	Description	Qty	Price	Total
F100374939	JACK, 68.5" CENTER QUICK DROP STABIL	1.00	94.88	94.88
Subtotal for Job #7:				254.88

Parts Total:	247.06
Labour Total:	928.00
Sublet Total:	0.00
Extras Total:	207.27
WORK ORDER TOTAL:	1,382.33

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Sep 2023

W/O: 71062
Promised Date: 29 JUL 23

Customer #: 1000
BASDEN'S AMERICAN RV,

