

# FOREST RIVER WARRANTY CLAIM FORM

|                         |            |                          |                   |
|-------------------------|------------|--------------------------|-------------------|
| DEALER ACCOUNT #        | 0005106    | CLAIM STATUS             | Authorized        |
| BASDEN RV CENTER INC    |            | CLAIM                    | 1597319           |
| DBA AMERICAN RV CENTER  |            | CLAIM ORIGIN             | WEB               |
| 600 E BASELINE ROAD     |            | ORIGINAL CLAIM ID        |                   |
| EVANSVILLE, IN 47725    |            | VIN                      | 5ZT2CAMB6PU041011 |
| USA                     |            | CHASSIS VIN              |                   |
|                         |            | MILEAGE                  | 0                 |
| Labor rate:             | \$160.00   | SITE/WAREHOUSE           | 103 / 103         |
| OWNER INFORMATION       |            | ITEM #                   | CAT231MKS-8       |
| DYLAN C SCHMITT         |            | DEALER RO #              | 71097             |
| 2023 BULLDOG LN         |            | CLAIM START DATE         | 07/10/2023        |
| Evansville, IN 47714    |            | CLAIM END DATE           | 01/01/1900        |
| USA                     |            |                          |                   |
| Retail Date of Purchase | 07/01/2023 | WARRANTY EXPIRATION DATE | 07/01/2024        |

## Claim Line Details

### Labor

Line# 1

#### Operation Code

10-11-24-00-000205

#### Operational Description

Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Repair/  
No Tread Code

#### Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-07-10 08:24:50 :: YOU CAN SEE DYALIGHT UNDER  
THE SLIDE ROOM WHEN IT IS CLOSED ON BOTH SIDES BOTTOM SEAL ON SLIDEROOM DOWN ON ENDS  
REPOSITION SEAL AND GLUE IN PLACE

#### Model #

Serial #

#### Dlr Sub Hrs

0.35

#### Sub Labor Amt

\$56.00

#### Appr Hrs

0.35

#### Appr Labor Amt

\$56.00

#### Notes

AUTHORIZED AS REQUESTED

### Labor

Line# 2

#### Operation Code

01-30-102-001117

#### Operational Description

Trim Molding, each - Replace/Interior/Panels, Ceilings, & Interior  
Moldings

#### Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-07-10 08:26:00 :: THERE IS A BAR THAT HOLDS THE  
DINETTE TABLE UP IT FELL OFF NEED TO INSTALL THAT BACK UP STAPLES PULLING OUT CUT  
STAPLES OFF, DRILL POILET HOLES AND INSTALL WITH SCREWS, PUT SCREWS ON THE OTHER BOARDS  
AS STAPLES ARE LOOSE CLOSE UP UNIT AND PULL OUT

#### Model #

Serial #

#### Dlr Sub Hrs

0.80

#### Sub Labor Amt

\$128.00

#### Appr Hrs

0.40

#### Appr Labor Amt

\$64.00

#### Notes

EXCESSIVE AMOUNT REQUESTED  
CHANGED TO SIMILAR REPAIR TIME

## Submitted

|                 |          |
|-----------------|----------|
| Labor Amt       | \$184.00 |
| Parts & Freight | \$0.00   |
| Total           | \$184.00 |

## Approved

|                 |          |
|-----------------|----------|
| Labor Amt       | \$120.00 |
| Parts & Freight | \$0.00   |
| Total           | \$120.00 |

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.