

WARRANTY CLAIM # 71123
MANUFACTURER'S CLAIM #:

Inv #: 393910

WO #	Job #	Description	JOB INFORMATION
71123	7	THE FRONT ACCESS DOOR RUBBER SEAL IS RIPPED IN THE LOWER LEFT CORNER Sill is tore. Ordered sills	
71123	1	WHEN LOOKING INTO THE FRONT (UNDER PIN BOX) STORAGE COMPARTMENT, YOU CAN SEE THE GROUND WHEN YOU LOOK AT THE LOWER DOOR SIDE CORNER. Sea light coming from the inside the compartment. Put foam in crack and silicone with black silicone.	
71123	2	SEVERAL OF THE LATCHES AND LOCKS DO NOT CATCH PROPERLY AND THEY EITHER FIT LOOSLEY, OR THEY SPIN ALL THE WAY AROUND. Loose locks. Check every compartment door and tighten them all down and make sure they work properly.	
71123	3	THE WATER HEATER DOOR DOES NOT LINE UP PROPERLY WHEN IT CLOSES. IT LOOKS AS THOUGH THEY TRIED TO CAULK AROUND THE DOOR WHEN THEY INSTALLED IT. IT ALSO LOOKS LIKE CAULK WAS PUT IN AREAS INSIDE THE WATER HEATER COMPARTMENT THAT WAS NOT NEEDED. Sloppy silicone. Heat it up and remove silicone. Silicone where needed. Straightened doors good as you can be.	
71123	4	THE INSIDE FLOOR OF THE KITCHEN CABINET WITH THE GLASS DOORS IS	

Claim : 71123

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
              LOOSE AND UNEVEN. THERE ARE LIGHTS ATTACHED TO THE BOTTOM SIDE
              THAT FLICKER BECAUSE THE BOTTOM OF THE CABINET SMASHES THE WIRING
              FOR THE LIGHTS.
              Missing staples.
              Staple down panel and make sure wasn't loose.

71123      5      THE OFF DOOR FRONT BOTTOM SIDE IS MISSING STAPLES. THIS IS JUST
              UNDER THE OUTER FRONT EDGE WHERE THE DIAMOND PLATE SIDING
              ATTACHES TO THE WOODEN FRAME. THE WOODEN PANELING IS NOT SECURED
              PROPERLY ON THE OFF DOOR SIDE. CUSTOMER ALSO POINTED OUT THAT
              BARE WOOD IS EXPOSED TO THE ELEMENTS ON BOTH SIDES.
              Staples.
              Remove loose staples. Remove screws holding on diamond plate.
              Take underbelly tape and cover all raw wood.. Put screws back.

71123      8      THE RUBBER AROUND THE OFF DOOR PROPANE DOOR IS RIPPED ON THE
              RIGHT SIDE OF THE DOOR OPENING
              Seals tore
              Ordered seals

71123      9      THE OUTSIDE KITCHEN DOOR FITS LOOSLY TOWARDS THE FRONT. THE REAR
              LATCH PULLS THE DOOR IN MUCH TIGHTER THAN THE FRONT LATCH.
              Loose door.
              Unscrewed the top set screws and moved plastic inserts over to
              make get tight.

71123      12     LOOK AT THE SCREWS ON THE EXTERIOR OF THE CHROME FURNACE COVER.
              SOME ARE STRAIGHT AND SOME ARE CROOKED.
              Screws.
              Remove screws and straightened out.

71123      13     THE FRONT SPEAKER ON THE DOOR SIDE IS NOT SEALED PROPERLY AROUND
              THE OUTSIDE.
              Speaker.
              Silicone around speakers.

71123      15     THERE IS A BRACE RUNNING FROM THE FRAME TO THE J WRAP ON THE DOOR
              SIDE REAR OF THE CAMPER. CUSTOMER WOULD LIKE THE SAME BRACE ADDED
              TO THE OFF DOOR SIDE.
              Missing brace.
              Install brace.

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
321161      7      Seal - D Seal - EPDM - .57" x .4 16.00      0.37      5.92

```

Claim : 71123

```
*****
Part No      Job#  Description      PARTS      Qty      Price      Total
*****
```

```
*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
```

Z990	7	MISC LABOUR CODE (EXTERNAL)	0.30	160.00	48.00
Z990	7	MISC LABOUR CODE (EXTERNAL)	0.00	160.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)	0.00	160.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)	0.00	160.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)	0.10	160.00	16.00
Z990	2	MISC LABOUR CODE (EXTERNAL)	0.25	160.00	40.00
Z990	2	MISC LABOUR CODE (EXTERNAL)	0.25	160.00	40.00
Z990	3	MISC LABOUR CODE (EXTERNAL)	0.10	160.00	16.00
Z990	4	MISC LABOUR CODE (EXTERNAL)	0.10	160.00	16.00
Z990	5	MISC LABOUR CODE (EXTERNAL)	0.15	160.00	24.00
Z990	5	MISC LABOUR CODE (EXTERNAL)	0.15	160.00	24.00
Z990	8	MISC LABOUR CODE (EXTERNAL)	0.30	160.00	48.00
Z990	8	MISC LABOUR CODE (EXTERNAL)	0.00	160.00	0.00
Z990	9	MISC LABOUR CODE (EXTERNAL)	0.10	160.00	16.00
Z990	12	MISC LABOUR CODE (EXTERNAL)	0.05	160.00	8.00
Z990	13	MISC LABOUR CODE (EXTERNAL)	0.10	160.00	16.00
Z990	15	MISC LABOUR CODE (EXTERNAL)	0.10	160.00	16.00

```

Parts Total:      5.92
Labour Total:     328.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 333.92

Customer Signature: _____

Date: _____