

e-Authorization

7/24/20
01:18:03

Authorization number PA03483352 Reference no: 71137 Status: Approved Approved by RassD Approved date 7/13/2023
 Billing Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTZRR27PS370286 4/19/2023
 600 E Baseline Rd
 Evansville, IN 47725

Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5100506B Breaker, 12V Mini	0.00	0.40	0.30		1	0.30	Complaint: THERE IS NO POWER AT ALL TO THE FRONT LEVELING JACKS AND REAR WON'T LIFT BUT WILL RETRACT Cause: Faulty circuit breaker Correction: Ran a test wire to jump the circuit breaker. Jack's worked while jumping the circuit breaker. Check continuity on circuit breaker and would not work. Is circuit breaker was a six amp. Put in a thirty amp circuit breaker. CHECKED REAR JACKS COULD NOT RECREATE PROBLEM ON REAR JACKS. REAR JACKS WENT UP AND DOWN NO PROBLEMS.
2	3202016A Panel - Interior W.	0.00	0.20	0.20		1	0.10	Complaint: THE INTERIOR WALL PANEL ON THE OFF DOOR SIDE OF THE BEDROOM IS BULGING OUT. Cause: Not enough staples to whole panel to stud. Correction: Stapled panel back to stud. Put more Staples in the panel then factory did. Taped the wall panel with wall tape.
3	6104415A Shower/Tub - Doc	0.00	1.00	0.50		1	0.50	Complaint: THE SHOWER LEAKS ALL AROUND WHERE THE DOOR MEETS THE BOTTOM OF THE SHOWER PAN. Cause: Shower glass to floor pan not properly sealed. Correction: When water is being sprayed on glass, water comes out the bottom of the glass and trim and onto the floor. Cleaned Around the glass and then silicone. Will let silicone dry water test later. After an hour checked the shower pan after being siliconed. Sprayed water along the glass and bottom. No water ran out onto the floor.
4	3200814A Door - Interior Silic	0.00	0.30	0.20		1	0.20	Complaint: SLIDING DOOR CAME OFF HINGE Cause: Sliding HINGE pulled away from door Correction: Pull-down trim above door. Unclipped the other half of the door from the hinge. Unclip the other Hinge that was not attached to the door. The skirt hangs back to door then stuck door back up and track, followed by the trim. Door slides with ease. Took pictures.

paper claims only use one pre-authorization number per warranty claim for
 multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

e-Authorization

7/24/20
01:18:03

Job Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
				1.20				

3-Authorization number PA03483352

For paper claims only use one pre-authorization number per warranty claim for

multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the