



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71137
Promised Date:
06/11/23

CUSTOMER WORK ORDER

WO #: 71137 (Appointment Date: 10 JUL 2023 - Time: 09:00am)

Customer: 53772 - SPEGAL, CRYSTAL - Stock #:
(812) 457-0820 Stock Desc: 2023 TT CROSSROADS
Tag: ZINGER
Author: BJW Chassis #:
Location: 0717 BJ LOOK OVER RO Serial #: 4YDTZRR27PS370286
MAKE SURE YOUR HAPPY WITH (E) Mileage:
JOBS Licence:

Invoice #: 394065
Date In: 11 JUL 23
Promised: 29 JUL 23
Date Sched:
Completed: 18 JUL 23
Warr. Date:



Job #1 - Warranty

COMPLAINT: THERE IS NO POWER AT ALL TO THE FRONT
LEVELING JACKS AND REAR WON'T LIFT BUT
WILL RETRACT

CAUSE: Faulty circuit breaker

CORRECTION: Ran a test wire to jump the circuit breaker. Jack's worked while jumping the circuit breaker.
Check continuity on Circuit breaker and would not work. Is circuit breaker was a six amp. Put in a thirty amp
circuit breaker. CHECKED REAR JACKS COULD NOT RECREATE PROBLEM ON REAR JACKS. REAR
JACKS WENT UP AND DOWN NO PROBLEMS.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	48.00

Parts

Part #	Description	Qty	Price	Total
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	3.82	3.82

Subtotal for Job #1: 51.82

Job #2 - External

COMPLAINT: CUSTOMER AWOKE TO A FLOODED WATER
COMPARTMENT AND AROUND THE PEX TUBBING.
WATER WAS RUNNING OUT OF THE
UNDERPINNING.

CAUSE: If the sink stopper is in the sink and the water is on will cause the sink to overflow

CORRECTION: Put water in the fresh tank then turn on the water pump. Turned on the outside kitchen
faucet. Found sync stopper insink. Found no leaks. Turn off the water pump, then hook up city water to
check for leaks. no leaks were found. cut the underbelly to check for any water that was settling. Bone dry
in the underbelly. Check for water leaks no water leaks found. Taped the underbelly backup.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Customer #: 53772
SPEGAL, CRYSTAL





Job #3 - Warranty

COMPLAINT: THE INTERIOR WALL PANEL ON THE OFF DOOR SIDE OF THE BEDROOM IS BULGING OUT.

CAUSE: Not enough staples to hold panel to stud.

CORRECTION: Stapled panel back to stud. Put more Staples in the panel than factory did. Taped the wall panel with wall tape.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	32.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Subtotal for Job #3:			32.00

Job #4 - Warranty

COMPLAINT: THE SHOWER LEAKS ALL AROUND WHERE THE DOOR MEETS THE BOTTOM OF THE SHOWER PAN.

CAUSE: Shower glass to floor pan not properly sealed.

CORRECTION: When water is being sprayed on glass, water comes out the bottom of the glass and trim and onto the floor. Cleaned Around the glass and then silicone. Will let silicone dry water test later. After an hour checked the shower pan after being siliconed. Sprayed water along the glass and bottom. No water ran out onto the floor.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR	SAR	80.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00

Parts				
Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	16.59	16.59
Subtotal for Job #4:				96.59

Job #5 - Warranty

COMPLAINT: SLIDING DOOR CAME OFF HINGE

CAUSE: Sliding HINGE pulled away from door

CORRECTION: Pull-down trim above door. Unclipped the other half of the door from the hinge. Unclip the other Hinge that was not attached to the door.. The skirt hangs back to door then stuck door back up and track, followed by the trim. Door slides with ease. Took pictures.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	32.00
Subtotal for Job #5:			32.00

Parts Total:	20.41
Labor Total:	192.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	212.41

