



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71156
Promised Date:
09/11/23

CUSTOMER WORK ORDER

WO #: 71156

Customer: 53835 - ROBLING, DALE L. -
812-484-7796

Tag:

Author: PH

Location: 0925 CHECK PREAUTH

Stock #: 10767

Stock Desc: 2023 TT COACHMEN
CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC5PK006057

Serial #: 5ZT2CAEC5PK006057

Mileage:

Licence:

Invoice #:

Date In: 13 JUL 23

Promised: 29 JUL 23

Date Sched:

Completed: 22 SEP 23

Warr. Date: 13 JUL 23

Job #1 - Warranty

COMPLAINT: WATER HEATER DOOR ALL SCRATCHED UP. NEEDS REPLACED.

CAUSE: Door

CORRECTION: Wrong size door in parts (10 gallon door)

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00

Parts

Part #	Description	Qty	Price	Total
140066	6261AEB BLK WH DOOR - SUBURBAN SURFA	1.00	39.68	39.68

Subtotal for Job #1: 119.68

Job #2 - Warranty

REPLACE TREAD TAPE ON STEPS. COVERED WITH PUTTY TAPE FROM FACTORY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00

Subtotal for Job #2: 32.00

Job #3 - Warranty

COMPLAINT: ALL INTERIOR LIGHTS FLICKER BAD WHEN OPERATING WATER PUMP

CAUSE: PUMP

CORRECTION: CAN NOT ACSESS PUMP FROM WATER HEATER ACSESS KOLE UNDER BED HAVE O UNLOAD CUSTOMER STUF FROM COMPARTMENT AND CLIMIN COMPARTMENT, REMOVE ACSESS PANELS AND TEST PUMP, DISCONET PUMP AND WIRE IN TEST PUMP, (SHURFLO) AND TEST LIGHTS ONLY FLASH WHEN PUMP COMS ON AND NOT WHEN RUNNING,

Replace pump with shufflo pump

Load customer stuff

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00



Customer #: 53835
ROBLING, DALE L.



Z990 MISC LABOUR CODE (EXTERNAL) JP 0.00

Parts

Part #	Description	Qty	Price	Total
333426	Pump - Water - Revolution - 12V - 3 GPM - 55 PSI	1.00	56.25	56.25

Subtotal for Job #3: 136.25

Job #4 - Warranty

COMPLAINT: CHECK THE A/C MAKING A RATTLE SOUND

CAUSE: Foil tape loose in air box

CORRECTION: Remove loose tape and install new tape put air box back together

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	94.40
Z990	MISC LABOUR CODE (EXTERNAL)	JP	1.60

Subtotal for Job #4: 96.00

Job #5 - Warranty

COMPLAINT: LOOK AT THE FRIDGE NOT SITTING IN THE SPOT LEVEL

CAUSE: Top mounting bracket pushing top of refer in

CORRECTION: Remove trim, remove mounting screws remove top mounting bracket make new bracket to bring top of refer out paint bracket and install, install trim

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00

Subtotal for Job #5: 160.00

Parts Total: 95.93
 Labour Total: 448.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 543.93

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Sep 2023

W/O: 71156
Promised Date: 29 JUL 23



Customer #: 53835
ROBLING, DALE L.

