



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71201



CUSTOMER WORK ORDER

WO #: 71201 (Appointment Date: 19 JUL 2023 - Time: 04:30pm)

Customer: 50124 - NELSON, JENNIFER
N. - 812-632-8622

Tag:
Author: PH

Location: 0725 CHECK PREAUTH

Stock #: 11011

Stock Desc: (11011) 2023 FOREST
RIVER CHEROKEE GREY WOLF
26DBHBL

Chassis #: 4X4TCKB21PK085955

Serial #: 4X4TCKB21PK085955

Mileage:

Licence:

Invoice #:

Date In: 19 JUL 23

Promised:

Date Sched:

Completed: 24 JUL 23

Warr. Date: 13 JAN 23

Job #1 - Warranty

COMPLAINT: BATHROOM ENTRY DOOR IS LEAKING

CAUSE: rear door leaking

CORRECTION: took off cover on top of door to look at seal on top and it is sealed put cover back on and sealed,im going to let dry and do a water test.did water test for a hour with sprinkler on door and no leaks.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH | 48.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH | 0.00 |

Subtotal for Job #1: 48.00

Job #2 - Warranty

COMPLAINT: THE BOARD ON THE BOTTOM OF THE SLIDE ROOM RUBS THE FLOOR. HE CAN HEAR IT

CAUSE: trim

CORRECTION: took off trim board under slideroom on inside and peeled back fabric and cut a half inch off and stapled fabric back and installed ran room in and out and it dosent hit now,might mention to customer not to put so much weight under table,to much weight could cause damage later down the road to slide.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH | 48.00 |

Subtotal for Job #2: 48.00

Job #3 - Warranty

COMPLAINT: THE GASKET ON THE FRONT OF THE SLIDE DOES NOT TOUCH THE SLIDE

CAUSE: slide front wiper seal not touching.

CORRECTION: ran in and out and part of seal is not touching in middle,having ben contact forest river to see what can be done.forest river was no help,jacked camper in down position and ran room in while james purhed slideroom to front to slide it forwards,ran in and out to pull twards front and now room is touching seals,need ben to get ahold of bal to find out on this,there is no side to side things to hold camper from going one side to another it is a glide room. got with bal slide and they sent us a letter stating that is how you adjust room.

Labor



Customer #: 50124
NELSON, JENNIFER N.



| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|--------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH | 116.80 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH | 43.20 |

Subtotal for Job #3: 160.00

W/O: 71201

Parts Total: 0.00
 Labour Total: 256.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 256.00



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 24 Jul 2023

Customer Signature : _____

Customer #: 50124
 NELSON, JENNIFER N.

