



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71291
Promised Date:
06 AUG 23



Customer #: 45474
KITCHEN, JAMES D.



CUSTOMER WORK ORDER

WO #: 71291 (Appointment Date: 31 JUL 2023 - Time: 03:00pm)

Customer: 45474 - KITCHEN, JAMES D. - Stock #: 10883

812-589-9665

Tag:

Author: BJW

Location: 0910 CHECK PREAUTH

Stock Desc: 2022 TT FOREST RIVER

CHEROKEE WOLF PUP 16FQ

Chassis #: 5ZT2CKEC8NY024410

Serial #: 5ZT2CKEC8NY024410

Mileage: 0

Licence:

Invoice #: 396025

Date In: 31 JUL 23

Promised: 05 AUG 23

Date Sched:

Completed: 06 SEP 23

Warr. Date: 28 NOV 22

Job #EXPRESS - External

COMPLAINT: EXPRESS ROOF AND EXTERIOR SEAL AND SEAM INSPECTION

CAUSE: Tech suggests uv treatment. Will include cleaning of roof, outside of camper and applying uv protective coating.

CORRECTION: Customer decided not to do uv treatment. Applied dicor as needed,

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #EXPRESS: 0.00

Job #2 - Warranty

COMPLAINT: THE WATER HEATER IS NOT PERFORMING PROPERLY ON LP.

CAUSE: Turned on gas. Turned on water heater. Water heater ignites but doesn't have sufficient gas. Removed the heat shield from burner chamber. removed Hardware for gas valve and burner tube. Removed orifice to make sure it was clear of debris. Took an air hose and blew out everything outside of chamber and burner tube. Installed orifice and burner tube. Tested water heater and its still not getting enough fuel. Need to replace gas valve. Took pictures of gas valve and wrote up parts order sheet. Went back and checked gas lines. Gas line is pinched and is causing restriction for water heater. Line needs replaced. Received gas manifold. Removed line from new manifold. Removed old line from water heater. Pulled line through compartment and floor. Ran new line. Secured to block manifold and water heater. Sealed access hole with silicone. Pulled unit inside and ran water heater on gas. Water heater ran without any issues. Cleaned mess.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	200.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	160.00





Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
161255	GAS VALVE FOR 5243A WATER	1.00	60.73	60.73
F100250607	LP, MANIFOLD ASSEMBLY FOR 16FQ WITHO	1.00	106.70	106.70

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-VALVE	1.00	6.99	6.99
FRT	UPS-MANIFOLD	1.00	17.23	17.23

Subtotal for Job #2: 551.65

Job #3 - Internal

COMPLAINT: THE TOILET ROCKS BACK AND FORTH AND DOESN'T SEEMED TO BE SECURED TO THE FLOOR PROPERLY.

CAUSE: .

CORRECTION: Tightened nuts on mounting bolts. Toilet has normal amount of movement.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: THE VENT FAN SWITCH QUIT WORKING ON CUSTOMER'S RECENT CAMPING TRIP.

CAUSE: Button for fan was stuck.

CORRECTION: Cleaned button with window cleaner. Let sit and wiped off with rag. Tested switch multiple times. Switch is working.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #4: 0.00

Job #JACK - Internal

COMPLAINT: INSTALL ELECTRIC TONGUE JACK THAT WAS DAMAGED WHILE UNIT WAS HERE FOR SERVICE.

CAUSE: Broke jack.

CORRECTION: Removed jack and replaced with new.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #JACK: 0.00

Job #LP - External

COMPLAINT: FILL LP

CAUSE: Fill lp.



CORRECTION: 2 gallons.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	2.00	N/C	N/C

Subtotal for Job #LP: 0.00

Parts Total: 167.43
Labour Total: 360.00
Sublet Total: 0.00
Extras Total: 24.22

WORK ORDER TOTAL: 551.65

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Sep 2023

W/O: 71291
Promised Date: 05 AUG 23



Customer #: 45474
KITCHEN, JAMES D.

