

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71307
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 53860 - CANDACE S. HALL
Address: 400 WEST HICKORY DR ELLETTSVILLE, IN

47429

Phone: 812-322-1494

Stock Number: 10952 - 2024 CATALINA SUMMIT SERIES 164BHX 5ZT2CAEC2RK006293
VIN: 5ZT2CAEC2RK006293 HIN: SER#: 5ZT2CAEC2RK006293

Mileage: 0

Work Order Comp: 08 AUG 23

Auth. No:

Dealer #:

Warr. Date: 03 AUG 23

Work Order Date: 31 JUL 23

Inv #: 394967

WO # Job # Description JOB INFORMATION

71307 1 OUTSIDE COVER IS MISSING FOR EXHAUST FAN
vent
took out screws and pulled vent off and had to get all silicone
off of metal and putty once cleaned put putty on new vent and
installed vent and screwed in and siliconed all the way around.

71307 2 FRIDGE IS NOT TIED DOWN
frige
pushed ref back and took off trim around ref, got top piece for
ref and made new wooden piece, stapled in place, put ref back in
place and installed braces around feet and screwed in top piece
to hold ref, then installed trim around ref.

71307 3 FRIDGE SWITCH IS OUT OF THE WALL
switch
installed switch back in place.

71307 4 LIGHT FLICKER WHEN PUMP IS RUNNING
. lights flicker
TRACED WIRES AND TESTED AND FOUND THE VOLTAGE WAS DROPPING DOWN
TO 11 AT THE PUMP TRACED GROUND AND FOUND IT WAS GOING TO THE
GROUNDS AT THE BACK OF THE PANEL WHICH WAS SMALL WIRES AND I
BELEIVE THEY WAS GOING TO THE LIGHTS DONNIE GROUNDED THE
PUMP WIRE TO THE FRAME UNDER THE FLOOR AND NOW THE LIGHTS DO
NOT FLICKER. light were flickering when water pump was on, checked
voltage and it was ok, checked ground, ran ground wire to frame

Claim : 71307

 WO # Job # Description JOB INFORMATION

temperary and lights quit flickering,so i went unerneath and
 found ground wire to pump and slit into and put eyelets on them
 and grounded to frame,tracked wire to control box and wire is
 smaller,problem is fixed not big enough ground.

 Part No Job# Description PARTS Qty Price Total

 520261 1 Stove Vent Hood Exhaust Cover; 10 1.00 13.86 13.86

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.40 160.00 224.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00

Parts Total: 13.86
 Labour Total: 368.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 381.86

Customer Signature: _____

Date: _____