

# e-Authorization

8/30/20  
09:49:27

Authorization number PA03504901 Reference no: 71337 Status: Approved Approved by Johnj Retail sold on  
 VIN Approved date 8/30/2023

34 Basden's American RV Basden's American RV 4YDTH1N24N7247281 5/28/2022  
 600 E Baseline Rd  
 Evansville, IN 47725

PLU Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2302214D Compartment Doc	0.00		0.60		1	0.20	Complaint:3 compartment doors leaking Cause:lack of sealant Correction:reseal
2	2200114A Corner Moldings -	0.00		0.20		1	0.20	Complaint:corner molding ft ds leaking Cause:lack of sealant Correction:reseal KRV - Approved as a Goodwill gesture (non-warranty).
3	2200214A Corner Moldings -	0.00		0.20		1	0.20	Complaint:corner molding ft ods leaking Cause:lack of sealant Correction:reseal KRV - Approved as a Goodwill gesture (non-warranty).
4	4129314B Water Heater - At	0.00		0.30		1	0.30	Complaint:water heater door leaking Cause:lack of sealant Correction:KRV- reseal ONLY *no code available* KRV - Approved as a Goodwill gesture (non-warranty).
5	2300114D Entrance Door - I	0.00		0.20		1	0.20	Complaint:entrance door leak Cause:lack of sealant Correction:reseal KRV - Approved as a Goodwill gesture (non-warranty).
6	5101914A Light, Clearance	0.00		1.50		1	0.20	Complaint:7 lights leaking Cause:lack of sealant Correction:reseal KRV - Approved as a Goodwill gesture (non-warranty).
7	2315014A Window - 47" or L	0.00		2.00		1	0.50	Complaint:4 windows leaking KRV - Approved as a Goodwill gesture (non-warranty).

paper claims only use one pre-authorization number per warranty claim for  
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

**e-Authorization**

8/30/20  
09:49:27

Job Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
8 2302215F	Compartment Doc	0.00				1	0.20	Cause: lack of sealant Correction: reseal KRV - Approved as a Goodwill gesture (non-warranty). Complaint: LEAK CHECK UNIT USING SEAL TECH THIS IS NOT A SUBLET IT WAS DONE IN HOUSE THIS IS HOW I WAS TOLD TO PUT A PREAUTH IN Cause: HOOKED UP UNIT AND FIND THE LEAK THIS IS NOT A SUBLET IT WAS DONE IN HOUSE THIS IS HOW I WAS TOLD TO PUT A PREAUTH IN Correction: FOUND LEAKS ON THE UNIT AND SENT IN PREAUTH THIS IS NOT A SUBLET IT WAS DONE IN HOUSE THIS IS HOW I WAS TOLD TO PUT A PREAUTH IN
KRV- please submit a separate pre-auth for seal test- attention to tom woodiel								

3-Authorization number PA03504901 5.00

For paper claims only use one pre-authorization number per warranty claim for  
 multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the