

e-Authorization

9/8/20
01:08:03

3- Authorization number PA03523871

Reference no: 71340

Status: Approved

Approved by papca

Approved date 9/7/2023

4- Calling Name

Address

VIN

Retail sold on

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGM28R2500458				
Plu Root de operation of	Description	Sublet Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201816A Decorative Wood	0.00	0.10	0.10	1	0.10	Complaint:TRIM ON INSIDE STEPS IS LOOSE Cause:TRIM ON INSIDE STEPS LOOSE (NOD). Correction:Pulled old Brad nails. Repositioned trim on step. Secured in place with new Brad nails. Filled nail holes with matching putty. KRV – REPAIR ONLY approved.
2	3105006A Dinette Table - Fr	0.00	0.40	0.40	1	0.30	Complaint:BOTH DINETTE TABLE LEG BASES ARE BROKEN Cause:Table socket Correction:Removed broken table leg bases on floor. Installed new table leg bases on floor of kitchen slide out, KRV – Labor time adjusted allowing for proper repair procedure to be performed.
3	4147506B Oven - Furrion - A	0.00	1.00	0.50	1	0.10	Complaint:OVEN PILOT WILL NOT STAY ON Cause:Stove Correction:Checked all connections. Removed burner plate mounting screws and dropped out of way to get to pilot and thermocouple. Repositioned thermocouple. Turned pilot back on. Pilot now stays on. Remounted burner plate. Burner now comes on. KRV – REPAIR ONLY approved.
4	5101216A Coax, TV - Repair	0.00	0.60	0.60	1	0.30	Complaint:TEST TV WILL NOT PICK UP CHANNELS IN BEDROOM OR OUTSIDE Cause:No TV reception in bedroom and outside. Correction:Removed KEY TV box in side compartment. Found loose connections on coax connectors. Tightened connectors. Checked operationof test TV at both locations again. Both working now. KRV – REPAIR ONLY approved.

3- Authorization number PA03523871

1.60

r paper claims only use one pre-authorization number per warranty claim for
rple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the