

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71359
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11168A - 2021 CATALINA 283RKSLE 5ZT2CATBXXMX020187

VIN: 5ZT2CATBXXMX020187 HIN:

SER#: 5ZT2CATBXXMX020187

Mileage: 0

Work Order Comp: 21 AUG 23

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 04 AUG 23

Inv #: 395404

WO # Job # Description JOB INFORMATION

71359 2 RECALL - BRAKE AWAY WIRING WAS INSTALLED WRONG

I did not know that there was a labor line for the breakaway switch wiring recall. So approximately it took me almost 2 hours. Order number 71359. That is dedicated to the recall. I had to cut the underbelly peel away. All the unhooked the wires from the 12 V 30AM breaker underneath the unit. While doing so, both of them ended up, breaki had to get 2 new 30 amps. Install them. I had to make a jumper wire from the hot side of one to the other. As though the jumper plate would not fit. Because the 2 30 amps do not set right next to each other. I made a new loop end on the breakaway switch wire. I installed it on the battery disconnect. On the battery hot side. I put the plate back on the Junction box underneath the camper. Repaired the underneath of the camper was underbelly Tape Checked for proper breakaway operation when battery disconnect is in the off position. And everything worked as it should.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00

Parts Total: 0.00
Labour Total: 48.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 48.00

Customer Signature: _____

Date: _____

Claim : 71359

```
*****
Lab Code  Job#  Description          LABOUR                      Hrs      Rate      Total
*****
```