



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71360



Customer #: 48257
DIAMOND, LARRY K.



CUSTOMER WORK ORDER

WO #: 71360

Customer: 48257 - DIAMOND, LARRY K.
- 812-630-9592

Tag:

Author: PH

Location: DELIVERY 0808

Stock #: 11193

Stock Desc: 2023 TT COACHMEN
CATALINA 263FKDSLE

Chassis #: 5ZT2CARB8PX028638

Serial #: 5ZT2CARB8PX028638

Mileage:

Licence:

Invoice #:

Date In: 04 AUG 23

Promised:

Date Sched:

Completed: 19 AUG 23

Warr. Date: 04 AUG 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: final

CORRECTION: did final and everything on sheet also, touched up roof, checked lp system, electrical, appliances, and water system.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
13-3007	NUGEN 200Z.	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Internal

COMPLAINT: SWAP ALL 3 CAMERAS FROM TRADE

CAUSE: camera swap

CORRECTION: had to take off both side cameras on trade unit, and take off side lights on new camper we had to install cameras in middle of trailer, because they would not fit up front, because doors were to close to lights, wouldnt fit, talked to brian and that is where he wanted me to mount, had to clean up all silicone on camper all four lights, wired all four lights in and mount and silicone, next had to take off rear camera and take off cover on new camera and installed camera on new camper and install cover on old camper.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: SWAP TV FROM TRADE

CAUSE: tv

CORRECTION: took tv out of old unit and installed in new unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Printed On: 8/19/2023 11:31:38AM

© 2023 Integrated Dealer Systems



Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: SWAP BATTERIES FROM TRADE

CAUSE: batteries

CORRECTION: took out old batteries from trade and installed another battery box, installed batteries and hooked up wiring.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #3:			0.00

Job #4 - Internal

COMPLAINT: UPGRADE MATTRESS

CAUSE: mattress

CORRECTION: took out old mattress and put upstairs, took new mattress out of box and set inside and unrolled, cut plastic off of mattress and let it expand.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	N/C
Parts				
Part #	Description	Qty	Price	Total
5581	SHORT QUEEN MATTRESS - THOMAS PAYNE	1.00	N/C	N/C
Subtotal for Job #4:				0.00

Job #SWAP - Internal

SWAP CUSTOMER'S HITCHWORK

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	N/C
Parts				
Part #	Description	Qty	Price	Total
CUR21511	CUR21511 CLASS III/IV COATED GRIP 5/8IN HITCH PIN & CLIP PACKAGED	1.00	N/C	N/C
Subtotal for Job #SWAP:				0.00

Job #5 - Warranty

COMPLAINT: BATTERY DISCONNECT IS MISSING KEY

CAUSE: disconnect switch

CORRECTION: took off old disconnect switch and wires and installed new one and hooked up wires and secured.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	48.00
Parts				
Part #	Description	Qty	Price	Total
19-0509	700RV BATTERY DISCONNECT SWITCH	1.00	31.86	31.86



Subtotal for Job #5: 79.86

W/O: 71360

Parts Total: 31.86
Labour Total: 48.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 79.86

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Aug 2023



Customer #: 48257
DIAMOND, LARRY K.

