



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71397
Promised Date:
24 AUG 23

CUSTOMER WORK ORDER

WO #: 71397

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0831 BH TO CLOSE

Stock #: 11177

Stock Desc: 2024 5W ALLIANCE RV
PARADIGM 382RK

Chassis #: 7M5FP4225RB203619

Serial #: 7M5FP4225RB203619

Mileage: 0

Licence:

Invoice #:

Date In: 09 AUG 23

Promised: 31 AUG 23

Date Sched:

Completed: 31 AUG 23

Warr. Date:

Job #PDINFW - Internal

PDI - NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: THE HALF BATH FAUCET IS LEAKING. WATER IS COMING OUT AT THE HANDLE

CAUSE: Faucet

CORRECTION: Got pictures of faucet and filled out sheet to order, took off cold and hot line, unscrewed screws and unscrewed nut to pull faucet out, installed new faucet and nut and tightened down screws to hold in place, hooked up hot and cold line, all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
14377	BATHROOM SINK FAUCET	1.00	47.99	47.99

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	17.59	17.59

Subtotal for Job #1: 145.58



Customer #: 1000
BASDEN'S AMERICAN RV,



Job #2 - Warranty

COMPLAINT: THE MAX AIR FAN IN THE KITCHEN IS NOT WORKING

CAUSE: Fan in kitchen dosent work

CORRECTION: took fantastic fan shroud dwn to see if it had power and it does,took off controller on wall and found out it is wrong controller,it had a 8 pin controller in it it needs 6 pin controller,filled out sheet and give to bin for approval.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	40.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
10666	MAXAIR 4-SPEED WALL CONTROL	1.00	6.99	6.99

Subtotal for Job #2: 46.99

Job #3 - Internal

COMPLAINT: PIN MISSING ON EXTERIOR HANDRAIL

CAUSE: Pin

CORRECTION: Installed pin in handle

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
26074	PIN - QUICK RELEASE 1/4" DIA 2" FOR	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total: 54.98
 Labour Total: 120.00
 Sublet Total: 0.00
 Extras Total: 17.59
WORK ORDER TOTAL: 192.57

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 31 Aug 2023

