

e-Authorization

8/14/20
03:53:36 PM

3-Authorization number PA03505263 Reference no: 71398 Status: Approved Approved by papca Approved date 8/14/2023
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDFCGR24N2509449 6/17/2022
600 E Baseline Rd
Evansville, IN 47725

In Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
-------------------------	-------------	--------	-----------	-------------------	-----------------	-----	---------------	--------------------------------

1	6109515A Holding Tank Flue	0.00	1.20	1.20		1	0.30	Complaint: CUSTOMER ATTEMPTED TO FLUSH OUT THE BLACK TANK. THE WATER DID NOT GO INTO THE BLACK TANK, BUT IT DID START RUNNING OUT FROM THE UNDERBELLY. Cause: Water not connected Correction: Follow the line from the Black tank flush connection down to the tank and found that the connection was not connected to the black tank. Took pictures along the way. Remove the screws from the underbelly And did find that the line was not connected to the black tank. Screw the line fitting back to the tank and checked with water pressure to make sure it was not coming off and no leaks. Found no cause of why line was off. Put the underbelly back up and put the screws back in.
---	----------------------------	------	------	------	--	---	------	---

KRV – Approved as a Goodwill gesture (non-warranty).

3-Authorization number PA03505263 1.20

r paper claims only use one pre-authorization number per warranty claim for
able a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the