



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71399
Promised Date:
24 AUG 23

CUSTOMER WORK ORDER

WO #: 71399

Customer: 7028 - HARMON, EARL R. -
(270) 314-9349

Tag:

Author: BJW

Location: 0831 CHECK STATUS WITH
ZS

Stock #: 11115

Stock Desc: 2023 TT COACHMEN
CATALINA 323BHDSCKLE

Chassis #: 5ZT2CAXB4PX027263

Serial #: 5ZT2CAXB4PX027263

Mileage:

Licence:

Invoice #:

Date In: 09 AUG 23

Promised: 31 AUG 23

Date Sched:

Completed: 28 AUG 23

Warr. Date: 23 MAY 23

Job #1 - Internal

COMPLAINT: THERE IS A LEAK AT THE HOT WATER SIDE ON THE TOP OF THE BATHROOM FAUCET.

CAUSE: Pressurized system. Ran water on hot and cold. Couldn't see any signs of leaking. Leaving Pressurized to test.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: THE SHOWER FAUCET SEEMS TO BE LEAKING BEHIND THE SHOWER WALL AND THEN RUNNING OUT INTO THE FLOOR PAN OF THE SHOWER.

CAUSE: Pressurized system. Removed panel under shower pan. No signs of leaks anywhere. Leaving Pressurized to test. Let unit sit. no signs of leaks. Ran water over wall where it meets shower pan. No leaks present. Plumbing lines are also good.

CORRECTION: Couldn't replicate.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: ONE OF THE CABINET DOOR HANDLES ON THE DINING STORAGE COMPARTMENT IS MISSING A HANDLE.

CAUSE: Screw for handle has broke off inside handle. Need to replace.

CORRECTION: Removed damaged handle. Replaced with new one

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	14.40
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	1.60

Parts



Customer #: 7028
HARMON, EARL R.



Part #	Description	Qty	Price	Total
F100373439	BAR PULL, CABINET DOORS AND DRAWERS	1.00	1.14	1.14

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-HANDLE	1.00	17.25	17.25

Subtotal for Job #3: 34.39

Job #4 - Warranty

COMPLAINT: ONE OF THE CUSHIONS AT THE BACK OF THE DINING IS SCRATCHED/RIPPED.

CAUSE: Tear on seat cushion.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100307988	CUSHION, CENTER SEAT CUSHION TO DINE	1.00	180.26	180.26

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-CUSHION	1.00	10.01	10.01

Subtotal for Job #4: 222.27

Parts Total: 181.40
 Labour Total: 48.00
 Sublet Total: 0.00
 Extras Total: 27.26
WORK ORDER TOTAL: 256.66

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Aug 2023

W/O: 71399
 Promised Date: 31 AUG 23



Customer #: 7028
 HARMON, EARL R.

