

**e-Authorization**

9/8/20  
06:19:52 p

3-Authorization number PA03514773 Reference no: 71434 Status: Approved Approved by hull Retail sold on Approved date 8/23/2023  
 Naming Name Address VIN

34 Basden's American RV Basden's American RV 4YDTSGG18NW10356; 10/22/2022  
 600 E Baseline Rd  
 Evansville, IN 47725

Job operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4201514A Awning - Main - R	0.00	2.00	1.00		1	0.50	Complaint: CUSTOMER ADVISES THAT THE FRONT AWNING ARM DOES NOT PULL IN ALL THE WAY TO THE TRAILER Cause: Awning fabric wasn't made square or has shunk. Correction: Moved awning in and out to inspect the awning arms for damage. No damage was found. Moved awning out to max opening, found that the fabric was at different lengths, such as the awning arm at the front would hang lower. Put in 2 little bulb seals under the awning fabric to take up some slack to pull the awning in tighter on the front awning arm. Arm has pulled in closer.
3-Authorization number PA03514773				1.00				

KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

For paper claims only, use one pre-authorization number per warranty claim for

multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the